

---

# MC67NA Release Notes v 02.28.19

---

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Changes and Fixes](#)

[Part Number and Release Date](#)

---

## Introduction

Give your field workforce all the tools they need to work faster and smarter with the rugged 4G HSPA+ MC67. What can workers do with the MC67? Everything they need to get the job done. Access information in almost any backend system. Scan practically any bar code. Call a customer with an updated arrival window. Capture documents to enrich business intelligence and simplify recordkeeping. Take and send video and photos for real-time repair support. All at 4G HSPA+ speed. So whether your mobile workforce is fixing equipment, making deliveries, taking orders, performing inspections or issuing citations, they'll have all the tools they need to improve task efficiency, task accuracy and customer service, all in a single super-rugged device.

## Description

- Fusion Software 2.01.0.0.052R
- MSP Client v07.08.42
- WEHH 6.5 Professional AKU 29128 (5.3.12.16)
- Doc Capture 2.0
- DataWedge 3.5.14
- EA 2.52
- FPGA ver. 2.02
- WWAN FW version 2.003
- Audio version 18.84.00
- RIL 02.02.13.10

## Contents

- 67NAw65HenUL022819.ZIP v An UpdateLoader Package contained in a ZIP file. Use Instructions are contained within the ZIP file.
- 67NAw65HenAB022819.APF v A package file for deployment using AirBeam
- PH8P\_FW\_2.003Aud.zip - Firmware update

## Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC67NA	Microsoft WEHH 6.5 Professional

## Installation Requirements

1. MC67NA device must contain a released version of Microsoft WEHH 6.5 Professional

## **Installation Instructions**

Please see INSTRUCTIONS.txt which is part of 67NAw65HenUL012736.ZIP.  
If you had [CFE v1.3](#) installed, please run MasterUpdateCleaner.exe before upgrade.

## **Changes and Fixes**

- Update SE13 list date to April 9th, 2013
- Trouble printing on printpad or Oneil MF4TE Printer (SPR24018)
- Fix backlight auto mode operation
- Display orientation leads to black screen (SPR23885,SPR24385)
- Qwerty Keyboard does not emit sound when the V or Tab keys are tapped
- Phone turns off and cannot be turned back on (SPR23387)
- Disable suspend on face-down (SPR23513)
- Don't end data connection when voice call is ended
- Inclusion of document capture
- GPS crash (SPR23454)
- Phone does not always turn on when unit resumes from low battery
- Unit does not always suspend but appears off, causing battery drain
- Trigger wakeup not working correctly (SPR23950)
- Phone displays no service then locks up trying to launch phone dialer
- Scan beep affecting decode performance
- Qwerty keyboard does not emit sound when V or Tab keys tapped
- SD card detection issue
- Unable to set keystate to CTRL, ALT and NUMLOCK
- Improved Hands free echo cancellation
- Added CCX support
- The phone is stuck reporting continuously the same WAN IP and signal level when in fact is not even connected. (SPR23900)
- Fusion crash when run outside the depot (SPR23886)

## **Notes**

"Hotfix" patch for the following issues can be downloaded from Motorola Support Website

- SPR 24133: Strings inside SIM Toolkit are truncated.
- SPR 24409: Fix for exception when sdcard is not mounted after critical suspend.
- SPR 24395: Fix for exception when decode size exceeds scan buffer size.

## **Part Number and Release Date**

67NAw65HenAB022819.APF

67NAw65HenUL022819.ZIP

PH8P\_FW\_2.003Aud.zip

August 30, 2013