# MK500 Rev 01.30.0014

[Part #: 5Cxxc50BenOS013014]

## Contents

- Description
- Platform SDK Compatibility
- <u>Release Notes</u>
- Components
- Installation
- <u>Notes</u>

## Description

This package provides a complete software image for the MK500/MK590 products, in an OSUpdate package and individual hex files for use with TCM

Back to Top

# **Platform SDK Compatibility**

Windows CE Platform SDK v1.0 for MK500

Usage with older versions of the Platform SDK is not recommended.

Back to Top

**Release Notes** 

### Version v01.30.0014

1. Fixed flicking issue on the new LCD display.

### Version v01.30.0013

- 1. Fixed display flicker on new displays T35QM7117 and T35QM7118
- 2. Fixed USB download IPL and Monitor
- 3. Added support for NUMONYX Flash M58LR256 (0x880E)

#### Version v01.30.0012

1. Fixed new display flicker issue on new displays T35QM7117 and T35QM7118

### Version v01.30.0011

2. Fixed display flicker on new displays T35QM7117 and T35QM7118

### Version v01.30.0010

- 1. Fixed SPR 18730- Customer is unable to synch his MK500 to a SNTP server
- 2. Enable AlphaBlend
- 3. Include eastern European language support
- 4. Include support for new displays T35QM7117 and T35QM7118
- 5. Image kit (PixDLL) version 5.9.6.1003
- 6. Updated RD Client

### Version v01.30.0009

- 1. Fusion 2.61.0.0.013R
- 2. Fixed SPR 16864, value of subnet mask and default gateway were reversed in network status dialog
- 3. Fixed loss of Ethernet connection when SE950 engine is powered up

### Version v01.30.0008

- 1. Fusion 2.61.0.0.012R
- 2. Support Rev B hardware
- 3. New SDHX driver to support >4gb Micro SD cards
- 4. New version of AppLauncher
- 5. Include CalibSave.exe, launched at startup after calibration to persist calibration settings in a registry file
- 6. Set Default CPU mode to  $\ddot{\imath}_{\ell}$ <sup>1/2</sup>Max Performance $\ddot{\imath}_{\ell}$ <sup>1/2</sup>

- 7. Enable stereo output and adjust gains for maximum output volume
- 8. Fixed setting external RTC when manually setting the time via control panel
- 9. Fixed bug in kernel that could cause an exception when switching CPU speeds
- 10. Include support for AGFA fonts for localization

#### **Back to Top**

#### Components

Component	Filename
Windows CE Operating System	MK500c50BenOS013014.hex
Application	MK500c50BenAP014.hex
Platform	MK500c50BenPL014.hex
Partition Table	MK500c50BenPT002.hex
Splash Screen	MK500c50BenSC001.hex
Monitor/Boot loader	MK500c50XenMO0152XX.hex

#### **Back to Top**

## Installation

Installation can be accomplished by either using a MicroSD card are copying the installation files to the devices Temp folder and installing from there.

#### MicroSD Card Installation

- 1) Extract all files and folders from 5Cxxc50BenUP013012.zip
- 2) Copy the OSUpdate folder and all subfolders and files to the root of the MicroSD cards
- 3) Insert the MicroSD card into the MK500/MK590
- From the MK500/MK590 execute ï¿<sup>1</sup>/<sub>2</sub>My Deviceï¿<sup>1</sup>/<sub>2</sub> from the desktop
- 5) Open the  $\ddot{i}_{\ell}^{1/2}$ Storage Card $\ddot{i}_{\ell}^{1/2}$  folder
- 6) Open the OSUpdate folder
- 7) Double tap on the file �MK500c50BenColor\_SD.lnk�
- 8) Installation will begin and the device will reset when complete

#### Temp Folder Installation

- 1) Extract all files and folders from 5Cxxc50BenUP013012.zip
- 2) Establish an ActiveSync session
- 3) Copy the OSUpdate folder and all subfolders and the devices \Temp folder
- From the MK500/MK590 execute ï¿<sup>1</sup>/<sub>2</sub>My Deviceï¿<sup>1</sup>/<sub>2</sub> from the desktop
- 5) Open the  $\ddot{i}_{\ell}^{1/2}$ Temp $\ddot{i}_{\ell}^{1/2}$  folder
- 6) Open the OSUpdate folder
- Double tap on the file
  i¿<sup>1</sup>/<sub>2</sub>MK500c50BenColor\_Temp.lnkï¿<sup>1</sup>/<sub>2</sub>
- 8) Installation will begin and the device will reset when complete

Back to Top

## Notes

1. None

**Back to Top** 

Last revised: August 23, 2011