Release Notes - MC32N0 CE 7.0 Premium Rev C2 - 00.57.04-Localization

Introduction

Description

Contents

Device Compatibility Installation Requireme

Installation Instructions

Part Number and Release Date

Introduction

MC32N0 is Enhanced Mid-range, Industrial-grade Rugged Handheld

Affordable lightweight rugged mobile computing for key-based applications; Multiple field proven form factors; Gun; Compatibility with the MC3000 accessory ecosystem

Device Specifications:

- 1GHz Dual Core Processor
- 1GB RAM/4GB Flash memory
- CE7.0
- 3" Color display • 802.11 a/b/g/r
- SE4750
- IP54 sealing
- 5'Drop to concrete at room
- 500 1/2 meter Tumble
- New, improved battery installation and removal experience

OSUpdate Package 00.57.04 contains the SW required to update a MC32N0 CE 7.0 device to the RevC software.

Description

New features and enhancements in this release:

- 1. OS Windows CE 7.0 (07.00.2824)
- QFE Feb2016_Build2866_Updt56
- Fusion Radio SW Version 2.03.0.0.012R (FCC compliant & Support for IEEE 802.11r-Fast Transition)
- 4. RD Client Version 7.08.77
- 5. DataWedge Version 3_7_16_1510096. TelnetCE Version 7.3.239
- 7. emScript Version 1.3.11
- 8. CaptureDump Version 3,2,2
- 9. B2MClient (Elemez Version 1.0.0.381). Can be installed using \Windows \Elemez.cab 10. Asset Tracker Lite Version1.0

SPR FIXES

- SPR 26260 Resolved an issue where touch panel does not disable when its power state is set to D4
- SPR 27748 Memory improvements in scanner module
- SPR 28621 Resolved an issue where registry is not merging if semicolon is present in the path $\frac{1}{2}$
- SPR 26471 Resolved an issue where Kiosk mode/full screen mode is not working in IE
- SPR 27387 Resolved an issue where IE-checkbox control does not render
- SPR 27341 Resolved an issue in DataWedge where backslash in barcode does not work
- SPR 28406 Added support for NLS
- SPR 27173 Resolved an issue where code page encodings in IE was missing
- SPR 28299 Resolved an issue where "Add to Favorites" option missing from Favorites file menu in IE
- SPR 26489 Resolved an issue whereby audio being played out the headset for a short period of time when resuming from suspend
- SPR 28982 Resolved an issue where frmMain_Activated event was not triggered
- SPR 28140 Added support for MC32 in eMscript
- SPR 28478 Resolved an issue where device loses ethernet connection after swapping to different slots in ethernet cradle
- $SPR\ 28952 Resolved\ an\ issue\ where\ bluetooth\ headset\ audio\ stability\ issues\ were\ seen\ with\ TekSpeech\ Pro$
- SPR 29299 Resolved an issue where calibration data is not retained after warm boot
- SPR 29609 Resolved an issue where msmq dlls was not compatible with CE7 $\,$ SPR30852: Resolved an issue wherein garbled characters were displayed in IE
- SPR29610: Resolved an issue where Korean Character failed to Display in IE drop-down combo box
- $SPR28360: Resolved \ an issue \ where \ device \ hung \ after \ using \ SIP \ with \ pinyin \ input \ then \ hide \ it \ an input \ hide \ it \ and \ it$ SPR28957 : System.SR.DLL in localized language implemented on Localized images on CE7 MPA3
- SPR27276: Resolved an issue where UI was missing encryption options[fields were empty] on CE7[Jap loc image; BSP51.17]

Optional Hotfixes

The following SPR fixes are available as HotFixes which can be applied on top of this release

- SPR 28950 MC32N0-RL4HCHEIA Application hangs on SCAN_Enable
- SPR 28536 On Windows 10, when \Application is mounted as removable storage, file operations takes a very long time

Notes

To enable IE KIOSK feature reset the below registry keys to 0

- [HKEY CURRENT USER\Software\Microsoft\Internet Explorer\Main] "Task Bar"=dword:00000000
- "Status"=dword:00000000 "Command Bar"=dword:00000000
- "Animation"=dword:000000000
 "Menu Bar"=dword:00000000 "URL"=dword:00000000

- 1. 32N0c70BcpAB005704.APF Package file v00.57.04 AirBEAM- Simplified Chinese
 2. 32N0c70BcpAC005704.APF Package file with clean application v00.57.04 AirBEAM- Simplified Chinese
 3. 32N0c70BcpDC005704.izp Update Loader Image with clean application v00.57.04 Simplified Chinese
 4. 32N0c70BcpUP005704.zip Update Loader Image v00.57.04 Simplified Chinese
 5. 32N0c70BcpUP005704.zip Update Loader Image v00.57.04 Simplified Chinese
 6. 32N0c70BctAB005704.APF Package file v00.57.04 AirBEAM- Traditional Chinese
 7. 32N0c70BctAC005704.APF Package file with clean application v00.57.04 AirBEAM- Traditional Chinese
 8. 32N0c70BctC0005704.hex OS hex file V00.57.04 Traditional Chinese
 9. 32N0c70BctUP005704.zip Update Loader Image with clean application v00.57.04 Traditional Chinese
 10. 32N0c70BcdAB005704.APF Package file v00.57.04 Traditional Chinese
 11. 32N0c70BdcAB005704.APF Package file with clean application v00.57.04 AirBEAM- German
 12. 32N0c70BdeAC005704.APF Package file with clean application v00.57.04 AirBEAM- German
 13. 32N0c70BdeOS005704.hex OS hex file V00.57.04 German
 14. 32N0c70BdeUC005704.zip Update Loader Image with clean application v00.57.04 German

- 13.32N0c70BdeUS005704.hex OS hex file V00.57.04 German
 14.32N0c70BdeUC005704.zip Update Loader Image with clean application v00.57.04 German
 15.32N0c70BdeUP005704.zip Update Loader Image v00.57.04 German
 16.32N0c70BfrAB005704.APF Package file v00.57.04 AirBEAM- French
 17.32N0c70BfrAS005704.APF Package file with clean application v00.57.04 AirBEAM- French
 18.32N0c70BfrOS005704.hex OS hex file V00.57.04 French
 19.32N0c70BfrUC005704.zip Update Loader Image with clean application v00.57.04 French
 20.32N0c70BfrUP005704.zip Update Loader Image v00.57.04 French
 21.32N0c70BitAB005704.APF Package file v00.57.04 MiBEAM- Italian
 22.32N0c70BitAC005704.APF Package file v00.57.04 Italian
 23.32N0c70BitOS005704.hex OS hex file V00.57.04 Italian
 24.32N0c70BitUC005704.zip Undate Loader Image with clean application v00.57.04 Italian

- 23.32N0c70BitUC005704.hex OS hex file V00.57.04 Italian
 24.32N0c70BitUC005704.zip Update Loader Image with clean application v00.57.04 Italian
 25.32N0c70BitUP005704.zip Update Loader Image with clean application v00.57.04 Italian
 26.32N0c70BjpAB005704.APF Package file v00.57.04 AirBEAM- Japanese
 27.32N0c70BjpAC005704.APF Package file with clean application v00.57.04 AirBEAM- Japanese
 28.32N0c70BjpUC005704.hex OS hex file V00.57.04 Japanese
 29.32N0c70BjpUC005704.zip Update Loader Image with clean application v00.57.04 Japanese
 30.32N0c70BjpUP005704.zip Update Loader Image with clean application v00.57.04 Japanese
 31.32N0c70BkoAC005704.APF Package file with clean application v00.57.04 AirBEAM- Korean
 32.32N0c70BkoAC005704.APF Package file with clean application v00.57.04 AirBEAM- Korean
 33.32N0c70BkoOS005704.hex OS hex file V00.57.04 Korean
- 34.32N0c70BkoUC005704.zip Update Loader Image with clean application v00.57.04 Korean 35.32N0c70BkoUP005704.zip Update Loader Image with clean application v00.57.04 Korean 36.32N0c70BsiAB005704.APF Package file v00.57.04 AirBEAM- Spanish
- 30.32Noc70BsiAC005704.APF Package file with clean application v00.57.04 AirBEAM- Spanish 37.32Noc70BsiOS005704.APF Package file with clean application v00.57.04 AirBEAM- Spanish 38.32Noc70BsiUC005704.zip Update Loader Image with clean application v00.57.04 Spanish 40.32Noc70BsiUP005704.zip Update Loader Image v00.57.04 Spanish

Device Compatibility

This software release has been approved for use with the following Symbol devices

BILES
MC32N0-GI4HCHEIA
MC32N0-GL2HCHEIA
MC32N0-GL3HCHEIA
MC32N0-GL4HCHEIA
MC32N0-RL2HCHEIA

MC32N0	MC32N0-RL3HCHEIA
	MC32N0-RL4HCHEIA
	MC32N0-SI2HCHEIA
	MC32N0-SI3HCHEIA
	MC32N0-SI3SCHEIA
	MC32N0-SI4HCHEIA
	MC32N0-SL2HCHEIA
	MC32N0-GI3HCHEIA

Installation Requirements

MC32N0 device must contain a released version of CE 7.0 Software

Installation Instructions

- $1. \ \ \, Unzip\,ZIP\,file\,and\,copy\,its\,content\,(OSUpdate\,folder)\,to\,the\,\backslash Storage\,Card\,folder\\ 2. \ \, Place\,the\,SD\,card\,in\,the\,device\,to\,be\,upgraded$

- Place the device to be upgraded on A/C power supply.
 Navigate to the \Storage Card\OSUpdate and invoke the 32N0c70Ben_SD shortcut.

OR

- $1. \ \ Unzip\ ZIP\ file\ and\ copy\ its\ content\ (OSUpdate\ folder)\ to the\ \backslash temp\ folder$
- Place the device to be upgraded on A/C power supply.
 Navigate to the \temp\OSUpdate folder and invoke the 32N0c70Ben_TEMP shortcut.

Part Number and Release Date
32N0c70BcpAB005704
32N0c70BcpAC005704
32N0c70BcpOS005704
32N0c70BcpUC005704
32N0c70BepUP005704
32N0c70BctAB005704
32N0c70BctAC005704
32N0c70BctOS005704
32N0c70BctUC005704

32N0c70BdeAC005704 32N0c70BdeOS005704

32N0c70BctUP005704 32N0c70BdeAB005704

32N0c70BdeUC005704 32N0c70BdeUP005704 32N0c70BfrAB005704

32N0c70BfrAC005704 32N0c70B fr OS005704

32N0c70BfrUC005704 32N0c70B fr UP005704

32N0c70BitAB005704 32N0c70BitAC005704 32N0c70BitOS005704

32N0c70BitUC005704 32N0c70BitUP005704

32N0c70BjpAC00570432N0c70BjpOS005704

32N0c70BjpAB005704

32N0c70BjpUC00570432N0c70BjpUP005704 32N0c70BkoAB005704

32N0c70BkoAC005704 32N0c70BkoOS005704 32N0c70BkoUC005704

32N0c70BkoUP005704 32N0c70BsiAB005704 32N0c70BsiAC005704

32N0c70BsiOS005704

32N0c70BsiUC005704 32N0c70BsiUP005704

June13,2017