

---

# **Release Notes - MC32N0 CE 7.0 Standard Rev F – 10.57.32**

---

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

---

## **Introduction**

MC32N0 is Enhanced Mid-range, Industrial-grade Rugged Handheld.

Main features:

- Affordable lightweight rugged mobile computing for key-based applications; Multiple field proven form factors; Gun;
- Compatibility with the MC3000 accessory ecosystem

Device Specifications:

- 800MHz Dual Core Processor
- 512MB RAM/2GB Flash memory
- External Agent v2.57
- DataWedge v3.7.20
- MobiControl Stage v12.4.0
- TelnetCE v7.3.239
- CE7.0
- 3” Color display
- 802.11 a/b/g/n
- SE4750
- IP54 sealing
- 5’ Drop to concrete at room
- 500 ½ meter Tumble
- New, improved battery installation and removal experience

OSUpdate package 10.57.32 contains the SW required to update a MC32N0 CE 7.0 device to the RevF software.

## Description

### New features and enhancements in this release:

1. Fusion Radio SW Version 2.03.0.0.028R
2. Device Diagnostic Tool 2.0.0
3. QFE - June2018 Build2883 Updt68
4. Transport Layer Security (TLS) 1.2 is enabled (as part of QFE June2018 Build2883)

### SPR FIXES

- SPR 34846: Resolved an issue wherein MuteMic feature was not working.
- SPR 34726: Added Support for flash health monitor tool to retrieve flash id details for new 15nm emmc chips.
- SPR 34954: Resolved an issue wherein english image was not able to render some of the localization language scripts.
- SPR 35396: Resolved an issue wherein SE4850 Kepler Imager was not decoding right after battery swap
- SPR 35497: Resolved an issue wherein device reported exhibiting inconsistent FT roams within a MIST Systems cloud-based wireless environment
- SPR 34977: Resolved an issue wherein Bluetooth headset HS3100 was giving squeak/metallic sound when connected to MC32N0.
- SPR 34688: Resolved an issue wherein device was unable to connect to localized SSID.
- SPR 32569: Resolved an issue wherein device was unable to suspend when Soti agent is installed.

Please add the below registry to the device to fix the SPR 32569.

```
[HKEY_LOCAL_MACHINE\Comm\CXPort]
"NoIdleTimerReset"=dword:00000001
```

### Notes

1. To enable IE KIOSK feature reset the below registry keys to 0  
[HKEY\_CURRENT\_USER\Software\Microsoft\Internet Explorer\Main]  
"Task Bar"=dword:00000000  
"Status"=dword:00000000  
"Command Bar"=dword:00000000  
"Animation"=dword:00000000  
"Menu Bar"=dword:00000000  
"URL"=dword:00000000
2. To enable LED indicator feature for activity while scanning, set the below registry key to 1 (By default it will be set to 0)  
[HKEY\_LOCAL\_MACHINE\Drivers\BuiltIn\BarCodeReader\Settings]  
"EnableRedLed"=dword:00000001

## Contents

32N0c70BenUP105732.zip	OS Update Package
32N0c70BenUC105732.zip	OS Update Package with Clean application
32N0c70BenAB105732.APF	Airbeam Package
32N0c70BenAC105732.APF	Airbeam Package with Clean application
32N0c70BenOS105732.hex	OS hex binary image file

## Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC32N0	Windows CE7.0

## Installation Requirements

MC32N0 device must contain a released version of CE 7.0 Software

## Installation Instructions

1. Unzip ZIP file and copy its content (OS Update folder) to the \storage card folder
2. Place the SD card in the device to be upgraded
3. Place the device to be upgraded on A/C power supply.
4. Navigate to the \storage card\OS Update and invoke the 32N0c70Ben\_SD shortcut

OR

1. Unzip ZIP file and copy its content (OS Update folder) to the \temp folder
2. Place the device to be upgraded on A/C power supply.
3. Navigate to the \temp\OS Update folder and invoke the 32N0c70Ben\_TEMP shortcut

## Part Number and Release Date

32N0c70BenUP105732  
32N0c70BenUC105732  
32N0c70BenAB105732  
32N0c70BenAC105732  
32N0c70BenOS105732

Feb 28, 2019