
Release Notes - MC67NA Base v 03.57.14 - WEHH 6.5 Professional

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

Give your field workforce all the tools they need to work faster and smarter with the rugged 3.75G HSPA+ MC67NA Base. What can workers do with the MC67NA Base? Everything they need to get the job done. Access information in almost any backend system. Scan practically any bar code. Call a customer with an updated arrival window. Capture documents to enrich business intelligence and simplify recordkeeping. Take and send video and photos for real-time repair support. All at 3.75G HSPA+ speed. So whether your mobile workforce is fixing equipment, making deliveries, taking orders, performing inspections or issuing citations, they'll have all the tools they need to improve task efficiency, task accuracy and customer service, all in a single super-rugged device.

Description

Update Loader Image 03.57.14 contains the Software required to update an MC67NA Base device to the Rev C software release.

- WEHH 6.5 Professional AKU 29377

General Enhancements in 03.57.14:

- Fusion Software X_2.03.0.0.018R (ETSI RE-D compliant)
- SOTI MobiStage client version v12.4.0 (Build-1045)
- Support for new Micron 512MB RAM
Note: Older OS/BSPs (Older than 03.57.14) are prevented from being downloaded onto a unit with new hardware. There are safeguards in place in the new BSP to prevent installation of older BSPs.
- Added DDT Tool v1.03.09

SPR Fixes

- SPR 31218 - Resolved an issue where in the touch screen stops responding when using customer signature screen capture application
- SPR 28840 – Resolved an issue where in GPS speed and direction was not accurate on stationary device
- SPR 30615 - Resolved an issue where in Touch panel sporadic failure occurred
- SPR 32630 - Added WAN/RIL Logging Utility for MC67NA device as part of “Phone Info” applet
- SPR 32629 - Added GPS Logging Utility for All WM6.5 MC67 devices which support GPS
- SPR 31703 - Resolved an issue where in sometimes the scanner stays on when LCD mode was enabled in Datawedge

Contents

67NAw65HcpZP035714.zip	There are 2 packages included in a ZIP file - Partition Table & FPGA as one package and OS package along with instructions
67NAw65HcpAB035714.zip	A package file for OS package, WAN Firmware and Audio update deployment using AirBeam. Package includes the Upload instructions for MSP installation.
67NAw65HctZP035714.zip	There are 2 packages included in a ZIP file - Partition Table & FPGA as one package and OS package along with instructions
67NAw65HctAB035714.zip	A package file for OS package, WAN Firmware and Audio update deployment using AirBeam. Package includes the Upload instructions for MSP installation.
67NAw65HdeZP035714.zip	There are 2 packages included in a ZIP file - Partition Table & FPGA as one package and OS package along with instructions
67NAw65HdeAB035714.zip	A package file for OS package, WAN Firmware and Audio update deployment using AirBeam. Package includes the Upload instructions for MSP installation.
67NAw65HfrZP035714.zip	There are 2 packages included in a ZIP file - Partition Table & FPGA as one package and OS package along with instructions
67NAw65HfrAB035714.zip	A package file for OS package, WAN Firmware and Audio update deployment using AirBeam. Package includes the Upload instructions for MSP installation.
67NAw65HitZP035714.zip	There are 2 packages included in a ZIP file - Partition Table & FPGA as one package and OS package along with instructions

67NAw65HitAB035714.zip	A package file for OS package, WAN Firmware and Audio update deployment using AirBeam. Package includes the Upload instructions for MSP installation.
67NAw65HjpZP035714.zip	There are 2 packages included in a ZIP file - Partition Table & FPGA as one package and OS package along with instructions
67NAw65HjpAB035714.zip	A package file for OS package, WAN Firmware and Audio update deployment using AirBeam. Package includes the Upload instructions for MSP installation.
67NAw65HkoZP035714.zip	There are 2 packages included in a ZIP file - Partition Table & FPGA as one package and OS package along with instructions
67NAw65HkoAB035714.zip	A package file for OS package, WAN Firmware and Audio update deployment using AirBeam. Package includes the Upload instructions for MSP installation.
67NAw65HsiZP035714.zip	There are 2 packages included in a ZIP file - Partition Table & FPGA as one package and OS package along with instructions
67NAw65HsiAB035714.zip	A package file for OS package, WAN Firmware and Audio update deployment using AirBeam. Package includes the Upload instructions for MSP installation.

Device Compatibility

This software release has been approved for use with the following Zebra devices.

Device	Operating System
MC67NA Base	Microsoft WEHH 6.5 Professional

Installation Requirements

MC67NA device must contain a released version of Microsoft WEHH 6.5 Professional

Installation Instructions

Update Loader Package:

Note: “xx” is used to generalize for languages in the file below.

Standard Update Procedure -Device is cleaned of all persistent storage data. use this to update your device to a newer version of the OS.

1. Download the Update Loader Package 67NAw65HxxZP035714.zip
2. Unzip the contents of 67NAw65HxxZP035714.zip, after extraction 2 files are available 67NAw65HxxPT010400.zip, 67NAw65HxxUL035714.zip

3. Unzip each packages & install in the order 67NAw65XxxPT010400.zip, 67NAw65HxxUL035714.zip
 - a. Copy all files into either the \Temp folder on the device or at the root directory of a storage card.
 - b. If the contents are copied to SD card then place the SD card in the device to be upgraded.
 - c. Place the device to be upgrade on an A/C power.
 - d. Navigate to the SD Card or \Temp folder and invoke the program STARTUPDLDR.EXE.
 - e. The update will take about 5 minutes to complete. Please do not remove the device from A/C power during this time.
 - f. Once the download completes and the system reboots, the update is complete and the device is ready for use.
4. For detailed instructions please see "INSTRUCTIONS.TXT" which is part of 67NAw65HxxZP035714.zip

Airbeam Users:

Standard Update Procedure - This method erases all data in the Persistent storage of the device.

1. Download the Airbeam OSUpdate Package 67NAw65HxxAB035714.zip
2. Apply the Airbeam Update packages
3. Once the download completes and the system reboots, the update is complete and the device is ready for use.
4. For detailed instructions please see "MC67_MSP_Installation_Instructions.txt" which is part of 67NAw65HxxAB035714.zip for update through MSP

Downgrade to v02.57.04 or older:

Standard Downgrade Procedure:

1. Download the Update Loader Package 67NAw65HxxUL025704.zip or older
2. Unzip the package and copy all files into either the \Temp folder on the device or at the root directory of a Storage Card.
3. If the contents are copied to SD card then place the SD card in the device to be upgraded.
4. Place the device to be upgrade on an A/C power.
5. Navigate to the SD Card or \Temp folder and invoke the program STARTUPDLDR.EXE.
6. The update will take about 5 minutes to complete. Please do not remove the device from A/C power during this time.
7. Once the download completes and the system reboots, the update is complete and the device is ready for use.

Note:

- 1) Older OS/BSPs (Older than 03.57.14) are prevented from being downloaded onto a unit with new hardware. There are safeguards in place in the new BSP to prevent installation of older BSPs.
- 2) If OS is downgraded to earlier version than 02.57.04, then it is recommended to use RIL driver version 02.6.0.4. This is because WAN firmware 03.320 ARN 01.000.06 is compatible with RIL driver v02.6.0.4.
(Please refer to the below link for more information about this RIL driver 02.6.0.4 <https://www.zebra.com/us/en/support-downloads/software/drivers/mc67na-wan-drivers.html>)
- 3) By default, "Update Loader/Airbeam" packages will NOT delete contents of the Application partition.
 - If the user intends to clean application partition via update loader, "67NAw65HxxCA000001.bin" needs to be added to "pkgs.lst".
 - If the user intends to clean application partition via Airbeam, please use "67NAw65HxxCA000001.apf" package.
- 4) Please check "INSTRUCTIONS.TXT" on how to upgrade the WAN firmware to "03.320 ARN 01.000.06"
- 5) Before downgrading OS, delete "SotiMobiControlStage_WM.reg" file from application folder of the device to ensure SOTI client will get installed after downgrading the OS.

Part Number and Release Date

67NAw65HcpAB035714
67NAw65HcpZP035714
67NAw65HctAB035714
67NAw65HctZP035714
67NAw65HdeAB035714
67NAw65HdeZP035714
67NAw65HfrAB035714
67NAw65HfrZP035714
67NAw65HitAB035714
67NAw65HitZP035714
67NAw65HjpAB035714
67NAw65HjpZP035714
67NAw65HkoAB035714
67NAw65HkoZP035714
67NAw65HsiAB035714
67NAw65HsiZP035714

December 15, 2017