

# **Release Notes – Zebra Android 10**

### 10-30-02.00-QN-U06-STD-HEL-04 Release (NGMS)

## **Highlights**

This Android 10 GMS release 10-30-02.00-QN-U06-STD-HEL-04 covers L10A family of products. Please see Device Compatibility under Device Support Section for more details.

LifeGuard patches are cumulative and include all previous fixes that are part of earlier patch releases.

### Software Packages

Package Name	Description
HE_DELTA_UPDATE_10-30-02.00-QN-U06-STD-HEL-04.zip	LG Package Update

#### Security Updates

This build is Compliant up to Android Security Bulletin of June 01, 2022.

#### LifeGuard Update 06

- > This LG patch is applicable for 10-30-02.00-QG-U00-STD-HEL-04 BSP version.
  - New Features
    - Added support for querying touch mode, MX version and WLAN properties in OEM Info.
  - Resolved Issues
    - SPR46220 Resolved an issue wherein intermediate files were being retained along with snoop logs when BT Snoop logging was enabled in Rxlogger.
    - SPR45910 Resolved an issue wherein user was not able to enable Hotspot using EMDK/Stage Now after SIM card was removed..
    - SPR46231 Resolved an issue wherein upon scanning while in chrome browser resulted in tab switching instead of displaying barcode data.
    - SPR46101/45372 Resolved an issue wherein Velocity App updated via play store was getting deleted post an OS update on a device enrolled with MS INTUNE.



- SPR46227 Resolved an issue wherein BT headsets were experiencing distorted audio when it was
  operating in Narrow band frequencies.
- SPR46162 Resolved an issue wherein user was not able to use USB keyboard when access to USB storage from computer was disabled using MX Access Mgr

#### Usage Notes

- 10-16-10.00-QN-U120-STD-HEL-04 is not applicable for L10A devices with Display ZBR\_R47 and touch EXC86H82.
  - To identify display type, users can check 'ro.config.device.display' property using getprop command from adb.
    - Devices with new display ZBR\_R47 will have [ro.config.device.display]: [513]
    - Devices with display EP101R1912N1000TG will have [ro.config.device.display]: [2001]
  - To identify touch type, users can check 'ro.config.device.touch property using getprop command from adb.
    - Devices with new touch EXC86H82 will have [ro.config.device.touch]: [32770]
    - Devices with touch EXC3161 will have [ro.config.device.touch]: [32768]
- BMI270/ICM42607 Gyroscope/accelerometer sensor devices require 10-30-02.00-QN-U06-STD-HEL-04 or higher to ensure full G-sensor functionality.
- The installed Gyroscope/Accelerometer sensors can be identified either in SETTINGS or via ADB command:

#### SETTINGS

 Devices with BMI270/ ICM42607 Gyroscope/accelerometer sensor will list sensor type as BMI270/ ICM42607 on "Settings-->About phone-->SW components-->Gyroscope" or "Settings-->About phone-->SW components -- >Accelerometer".

#### ADB

- Check the ro.config.device.gyro & ro.config.device.accelerometer property using getprop command from adb.
- Devices with BMI270 Gyroscope/accelerometer sensor will have ro.config.device.gyro = 32 ro.config.device.accelerometer=120
- Devices with ICM42607 Gyroscope/accelerometer sensor will have ro.config.device.gyro = 260 ro.config.device.accelerometer=2052

#### Version Information

Below Table contains important information on versions

Description	Version
Product Build Number	10-30-02.00-QN-U06-STD-HEL-04
Android Version	10
Security Patch level	June 01, 2022



Component Versions

Please see Component Versions under Addendum section

### **Known Constraints**

- Picture quality of the image taken with 'Night Mode' in low-light conditions is poor.
- Trigger Modes: Presentation Read Mode is preferred over Continuous Read Mode. If using Continuous Read mode, use a lower illumination brightness setting (e.g., 2) to ensure the scanner can work without interruption.
- "Red Eye Reduction" feature disables the camera flash in the device. Hence, to enable the camera flash please disable the 'Red Eye Reduction' feature.
- EMM does not support agent persistence in OS dessert downgrade scenario.
- Reset packages of Oreo should not be used on devices running with A10 software.
- In-order to avoid any inconsistencies in Settings UI it is recommended to wait for a few seconds after the device boots up.
- Transparent blue overlay in camera view –numeric, character or ENTER key presses in camera view will
  make this blue overlay appear. The camera is still functional; however, the view is covered with the blue
  overlay. To clear this, press the TAB key to move the control to a different menu item or close the camera
  app.
- In case of an OS upgrade from a s/w version having higher security patch level to a s/w version having lower security patch level, user data will be reset.
- Unable to scan remote company network using ES file explorer over VPN.
- When phone app is being disabled using MDM and user tries to reboot the device, user might see Recovery Screen with "Try again" and "Factory data reset" options. Select option "Try again" to continue the reboot process. Do not select option "Factory data reset", as it will erase the user data.
- After upgrading from Oreo to A10, Device shows "SD card setup" notification, which is expected behavior from AOSP.
- After upgrading from Oreo to A10, staging fails on few packages, user must update package names accordingly and make use of the profiles or create new staging profiles.
- At the very first time, DHCPv6 enable through CSP is not reflecting until user disconnect/reconnect to the WLAN profile.
- Stagenow package name has been changed to com.zebra.devicemanager, This can cause issues with AE
  enrollments and locking down an unit like with EHS or EMM lockdowns. This Issue will be fixed on June 2022
  LifeGuard Release.

### **Important Links**

Installation and setup instructions (if the link does not work, please copy it to browser and try)
 Note: "As part of IT security best practices, Google Android enforces that the Security Patch Level (SPL) for the new OS or patch must be the same level or a newer level than the OS or patch version currently on the device. If the SPL for the new OS or patch is older than the SPL currently on the device, then the

device will enterprise reset and wipe all user data and settings including user network configurations and remote management tools which would render the device inaccessible over a network."

• Zebra Techdocs



• Developer Portal

## **Device Support**

### **Device Compatibility**

This software release has been approved for use on the following devices.

Device Family	Part Number	Device Specific Manuals and Guides
L10A	RTL10B1-xxxxxxxxCN Note: 'x' Stands for wild card for different configurations	L10A Home Page

### Addendum

### **Component Versions**

Component / Description	Version
Linux Kernel	4.4.205
AnalyticsMgr	2.4.0.1254
Android SDK Level	29
Audio (Microphone and Speaker)	0.35.0.0
Battery Manager	1.1.7
Bluetooth Pairing Utility	3.25
Camera	2.0.002
DataWedge	8.2.703
EMDK	9.1.4.3204
Files	10
License Manager and License Agent	version 6.0.8 and version 6.0.34.5.0.2
MXMF	10.5.0.89
NFC	NFC_NCIHALx_AR18C0.a.3.0
OEM info	9.0.0.699
OSX	QCT.100.10.12.69



RXlogger	6.0.4.0
Scanning Framework	28.11.5.2
StageNow	5.3.0.4
WLAN	FUSION_QA_2_1.3.0.044_Q
Baseband	W220429A_021.1-1-00889
Zebra Bluetooth Settings	2.3
Zebra Data Service	10.0.3.1001
Android Webview and Chromium	99.0.4844.58

# **Revision History**

Rev	Description	Date
1.0	Initial release	June 25, 2022