

Release Notes –“ SPR24621-After installing the SMSC cab file, Active Sync stops working ”

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

This patch resolves following issue: For MC91xx devices with SMSC cab installed on cold boot/clean boot stops active sync connection.

Description

1. After installing updated SMSC driver from Support Central for MC9190 WM/CE OS, Active Sync would stop working after a CleanBoot(WM)/Warmboot(WM/CE) / Coldboot(CE).
2. If an application or the user cleans up ‘\Application’ folder, this .cab solution has to be re-installed.

Contents

SPR24621_MC91xx_ActivesyncIssue_NoReboot.cab

SPR24621_MC91xx_ActivesyncIssue_WithReboot.cab

Device Compatibility

This software release has been approved for use with the following Symbol devices,

Device	Operating System
MPA2.0 devices – MC91xx	Windows Mobile 6.5,Windows CE 6.0

Installation Requirements

MC91xx Devices - WM Device with BSP 2.41.03, CE Device with 2.32.04

Installation Instructions

For NORMAL installation of the PATCH:

1. Copy “SPR24621_MC91xx_ActivesyncIssue_WithReboot.cab” file to device.
2. Deploy the solution by tapping on the .cab file.
3. After successful deployment of the.cab file, device will do an automatic warm boot.

For MSP or REMOTE installation of the PATCH:

Use “SPR24621_MC91xx_ActivesyncIssue_NoReboot.cab” for WM or CE device. This cab will not perform an automatic warm boot. MSP/Remote Installer is responsible for performing the warm boot.

Part Number and Release Date

SPR24621_MC91xx_ActivesyncIssue_NoReboot.cab
SPR24621_MC91xx_ActivesyncIssue_WithReboot.cab

November 07, 2013