
Release Notes - MC92N0 WEHH 6.5 Premium without MSOffice - v06.57.23 - Localization

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

The MC92N0-G is Symbol's premium industrial rugged handheld for in-premise scan intensive applications and is the next evolution of the MC9190-G product - the best selling rugged mobile computer in the industry - designed for such markets as retail, manufacturing, wholesale distribution and third-party logistics where intensive bar-code scanning takes place. The MC92N0-G is a true systems-level mobility solution, not just a mobile computer. The solution encompasses not only the new MC92N0-G itself, but also software tools, accessories/peripherals and mobility services to provide a true end-to-end solution.

Description

1. CPU Speed OMAP4430 ES2.3 - 1 GHz
2. Flash eMMC- 2GB
3. RAM - SDRAM - LPDDR2 1GB
4. Bluetooth: StoneStreetOne: BT Explorer 2.1.1 Build 28342
5. IST FW 1.13.0
6. PTT/Team Express v1.1.71.0000
7. DataWedge v3.7.16
8. B2MClient (Elemex Version 1.0.0.381).It can be installed using \Windows\Elemex.cab
9. eMscript version 1.3.11
10. Capture Dump version 3.2.2
11. External Agent - v2.57
12. PTT without having a wired or BT headset is no longer supported on MC92 units shipped from factory after July 1, 2016 because microphone was removed.

General Enhancements

1. Operating System: WEHH 6.5.3 AKU 29377

2. MobiControl Stage Agent v12.4.0
3. Fusion Radio SW Version 2.03.0.0.017R (FCC compliant & Support for IEEE 802.11r-Fast Transition)

SPR Fixes

1. SPR 31029 : Resolved an issue where low definition line was displayed on the home screen
2. SPR 30742 : Resolved an issue where the device had bluetooth headset audio stability problem with TekSpeech Pro
3. SPR 29938 : Resolved an issue where the device would reboot while performing a "safe battery swap", if the customer application was running in the background
4. SPR 29343 : Resolved an issue wherein the device was not able to establish the connection when assisted roaming feature (11k) was disabled in Cisco infrastructure
5. SPR 31306 : Resolved an issue wherein the beam doesn't go off upon testing for 20 times when the datawedge is set with LCD Mode
6. SPR 31359 : Resolved an issue where volume coming out of the headset speaker is not loud enough for MC92N0 WEH6.5 + HS3100 Bluetooth Headset

Notes

- Airwatch support is not available on German, Italian and Spanish localization images
- Microsoft Office will not be available in this release.
- SPR 24711:RF Apps performance can be improved by setting the below registry key for the specific <Nic Adapter Name> like XWING, SMSC9500, RndisFn, AsyncMac, PPTP, L2TP, PPPOE, LANNDS

*[HKEY_LOCAL_MACHINE\Comm\<NIC Adapter Name>\Parms\Tcpip]
"TcpAckFrequency"=dword:1*

Contents

92N0w65LcpAB065723.apf	AIRBEAM OS MC92N0 V065723 WITHOUT CLEANAPP - Simplified Chinese
92N0w65LcpAC065723.apf	AIRBEAM OS MC92N0 V065723 WITH CLEANAPP - Simplified Chinese
92N0w65LcpOS065723.hex	OS MC92N0 V065723 HEX IMAGE - Simplified Chinese
92N0w65LcpUC065723.zip	UPDATE OS MC92N0 V065723 WITH CLEANAPP - Simplified Chinese
92N0w65LcpUL065723.zip	UPDATE OS MC92N0 V065723 WITHOUT CLEANAPP - Simplified Chinese
92N0w65LctAB065723.apf	AIRBEAM OS MC92N0 V065723 WITHOUT CLEANAPP - Traditional Chinese

92N0w65LctAC065723.apf	AIRBEAM OS MC92N0 V065723 WITH CLEANAPP - Traditional Chinese
92N0w65LctOS065723.hex	OS MC92N0 V065723 HEX IMAGE - Traditional Chinese
92N0w65LctUC065723.zip	UPDATE OS MC92N0 V065723 WITH CLEANAPP - Traditional Chinese
92N0w65LctUL065723.zip	UPDATE OS MC92N0 V065723 WITHOUT CLEANAPP - Traditional Chinese
92N0w65LdeAB065723.apf	AIRBEAM OS MC92N0 V065723 WITHOUT CLEANAPP - German
92N0w65LdeAC065723.apf	AIRBEAM OS MC92N0 V065723 WITH CLEANAPP - German
92N0w65LdeOS065723.hex	OS MC92N0 V065723 HEX IMAGE - German
92N0w65LdeUC065723.zip	UPDATE OS MC92N0 V065723 WITH CLEANAPP - German
92N0w65LdeUL065723.zip	UPDATE OS MC92N0 V065723 WITHOUT CLEANAPP - German
92N0w65LfrAB065723.apf	AIRBEAM OS MC92N0 V065723 WITHOUT CLEANAPP - French
92N0w65LfrAC065723.apf	AIRBEAM OS MC92N0 V065723 WITH CLEANAPP - French
92N0w65LfrOS065723.hex	OS MC92N0 V065723 HEX IMAGE - French
92N0w65LfrUC065723.zip	UPDATE OS MC92N0 V065723 WITH CLEANAPP - French
92N0w65LfrUL065723.zip	UPDATE OS MC92N0 V065723 WITHOUT CLEANAPP - French
92N0w65LitAB065723.apf	AIRBEAM OS MC92N0 V065723 WITHOUT CLEANAPP - Italian
92N0w65LitAC065723.apf	AIRBEAM OS MC92N0 V065723 WITH CLEANAPP - Italian
92N0w65LitOS065723.hex	OS MC92N0 V065723 HEX IMAGE - Italian
92N0w65LitUC065723.zip	UPDATE OS MC92N0 V065723 WITH CLEANAPP - Italian
92N0w65LitUL065723.zip	UPDATE OS MC92N0 V065723 WITHOUT CLEANAPP - Italian
92N0w65LjpAB065723.apf	AIRBEAM OS MC92N0 V065723 WITHOUT CLEANAPP - Japanese
92N0w65LjpAC065723.apf	AIRBEAM OS MC92N0 V065723 WITH CLEANAPP - Japanese
92N0w65LjpOS065723.hex	OS MC92N0 V065723 HEX IMAGE - Japanese
92N0w65LjpUC065723.zip	UPDATE OS MC92N0 V065723 WITH CLEANAPP - Japanese
92N0w65LjpUL065723.zip	UPDATE OS MC92N0 V065723 WITHOUT CLEANAPP - Japanese

92N0w65LkoAB065723.apf	AIRBEAM OS MC92N0 V065723 WITHOUT CLEANAPP - Korean
92N0w65LkoAC065723.apf	AIRBEAM OS MC92N0 V065723 WITH CLEANAPP - Korean
92N0w65LkoOS065723.hex	OS MC92N0 V065723 HEX IMAGE - Korean
92N0w65LkoUC065723.zip	UPDATE OS MC92N0 V065723 WITH CLEANAPP - Korean
92N0w65LkoUL065723.zip	UPDATE OS MC92N0 V065723 WITHOUT CLEANAPP - Korean
92N0w65LsiAB065723.apf	AIRBEAM OS MC92N0 V065723 WITHOUT CLEANAPP - Spanish
92N0w65LsiAC065723.apf	AIRBEAM OS MC92N0 V065723 WITH CLEANAPP - Spanish
92N0w65LsiOS065723.hex	OS MC92N0 V065723 HEX IMAGE - Spanish
92N0w65LsiUC065723.zip	UPDATE OS MC92N0 V065723 WITH CLEANAPP - Spanish
92N0w65LsiUL065723.zip	UPDATE OS MC92N0 V065723 WITHOUT CLEANAPP - Spanish

Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC92N0	Microsoft WEHH 6.5 Classic Premium (without Microsoft Office)

Installation Requirements

- MC92N0 device must contain released version of Microsoft WEHH 6.5 Classic Premium Software
- Update Loader Image v06.57.23 contains the SW required to update a MC92N0-G Premium device having v05.57.17 or earlier versions and v00.55.11

Installation Instructions

1. Unzip the Update Loader Package (i.e 92N0w65LxxUL065723.zip/92N0w65LxxUC065723.zip) and copy its content to the \Storage Card folder.
2. Place the SD card in the device to be upgraded.
3. Place the device to be upgraded on A/C power supply.
4. Navigate to the \Storage Card folder and invoke the StartUpLdr.exe.
5. The update will take about 3-4 minutes to complete. Please do not remove the device from A/C power during this time.

OR

1. Unzip the Update Loader Package (i.e 92N0w65LxxUL065723.zip/92N0w65LxxUC065723.zip) and copy its content to the \Temp folder.
2. Place the device to be upgraded on A/C power supply.
3. Navigate to the \Temp folder and invoke the StartUpdLdr.exe.
4. The update will take about 3-4 minutes to complete. Please do not remove the device from A/C power during this time.

Part Number and Release Date

92N0w65LcpAB065723
92N0w65LcpAC065723
92N0w65LcpOS065723
92N0w65LcpUC065723
92N0w65LcpUL065723
92N0w65LctAB065723
92N0w65LctAC065723
92N0w65LctOS065723
92N0w65LctUC065723
92N0w65LctUL065723
92N0w65LdeAB065723
92N0w65LdeAC065723
92N0w65LdeOS065723
92N0w65LdeUC065723
92N0w65LdeUL065723
92N0w65LfrAB065723
92N0w65LfrAC065723
92N0w65LfrOS065723
92N0w65LfrUC065723
92N0w65LfrUL065723
92N0w65LitAB065723
92N0w65LitAC065723
92N0w65LitOS065723
92N0w65LitUC065723
92N0w65LitUL065723
92N0w65LjpAB065723
92N0w65LjpAC065723
92N0w65LjpOS065723
92N0w65LjpUC065723
92N0w65LjpUL065723
92N0w65LkoAB065723
92N0w65LkoAC065723
92N0w65LkoOS065723

92N0w65LkoUC065723
92N0w65LkoUL065723
92N0w65LsiAB065723
92N0w65LsiAC065723
92N0w65LsiOS065723
92N0w65LsiUC065723
92N0w65LsiUL065723

July 21, 2017