

---

# Release Notes - MC95X8 BSP 04.41.04 - WEH6.5 Professional

---

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

---

## Introduction

The MC9500-K raises the bar for premier rugged mobile computing, incorporating breakthrough ergonomic design and features to support the most demanding field mobility applications. Truly in a class of its own, this groundbreaking device is as different on the inside as it is on the outside. Building on signature MC9000 Series, the MC9500-K delivers a more rugged design, more data capture options, true WAN technology independence and application flexibility through customer-swappable WAN subsystems and keypads, more processing power and a game-changing approach to battery and backroom management - all in a lighter, sleeker and easier-to-use form factor.

MC95X8 BSP 04.41.04 SW release is based on the latest Microsoft Windows Embedded Handheld 6.5 Operating System and offers an enhanced user experience both in look and feel. This release supports 95X8 device with CMI display panels. It also supports Toshiba 1GB Nand Flash and the sku of both 128MB RAM/512 MB flash sku as well as the new extended memory sku which has 256MB RAM/1G flash as RevC release.

Update Loader Image 04.41.04 contains the SW required to update an MC95X8 CDMA Phone device to the Rev D software release.

This software is intended to be loaded and run on the MC95X8 CDMA Phone devices. It is important that care be taken to match the device configuration with the appropriate Update Loader package. If an incorrect Update Loader package is loaded, the device may fail to operate properly or even fail to boot.

## Description

### General Enhancements in 04.41.04:

- Monitor is modified to support CMI display on Old Main Board devices.
- Update loader is modified not to allow to downgrade to 4.41.03 on the devices having Old Main Board + CMI display.

### Enhancement till 04.41.03:

- Microsoft Windows Embedded Handheld 6.5 Professional (Build 29040.5.3.12)
- Team Express Client Licensed version v1.1.23-1102 included as a cab file
- Included MMAX Demo v5.0.12
- Datawedge v3.3.19
- WLAN Fusion version v3.00.2.0.019R
- MSP Agent 7.03.58, Airbeam 7.03.58, RD Client 7.03.58. (This software release has been tested on MSP 3.3 and passed MSP Compliance)
- WWAN CDMA MC5727 version:
  - a) RIL SW 3.25.0.0
  - b) SWI VSP Ver 1.25.0.0
  - c) OEM Aux Ver 0.40
  - d) Modem FW Ver: Sprint - 1.67.02 , Verizon - 1.67.03
- Support for Unified MSR driver: Unified MSR driver, abstracts out the HW layer, so that one single (unified) DLL could be used for all of the MSR devices.
- Config Tab dynamically populated with OS version WM6.1 / WM6.5 / WEH6.5.
- Added ability to suppress the pairing dialog box that shows up when using SS stack.
- Audio driver is modified to improve the audio quality during VOIP.
- Audio Registry changes to have general/default audio settings and to prevent overriding of speaker.
- Shift key will support only two states now instead of three states.
- SPR 19650: Incorrect smart Battery part Number reported via EMDK API.

- SPR 19313: The registry key to prevent the SD card from un-mounting when removing the battery does not work correctly.
- SPR 19345: Application launched with Startup.exe will get closed as soon as it launches.
- SPR 18796: DUT failed to scan barcodes with 50 characters.

### Features/Fixes in Camera/Scanning/Imager:

- **General Fixes:**
  - o Improvements to DPM datamatrix codes with new Pixdll 5.14.09.02 and supports DPM ROI Lite.
  - o Long range imager calibration for reading reflective barcodes at 30feet distance fixed.
  - o Added coupon report mode, which enable user to read old, interim and new coupon types. Also added new UPC/EAN param for selecting coupon report mode.
  - o The reflective code released for MC9190.
  - o Coupon report mode for old and new coupon codes.
  - o Added support for LCD mode with new reader param for LCD mode. LCD mode is supported only for SE4500 Rev B engines.
- **RS507:**
  - o RS507 was not sending the first disconnect notification to the application.

### WLAN - Fusion Release Notes v3.00.2.0.0019R:

- o SPR 20440: Correct issue where authentication would occasionally fail after cold boot.
- o SPR 19274: Fixed an issue where the WLAN radio would occasionally reset during high volume data transfers.
- o Fixed an issue where Wireless Status application displays an empty message box if WLAN is disabled via Microsoft SCMDM.
- o Fixed an issue where FIPS 140-2 self test would fail.
- o Added the user certificate hash override feature [Fusion API enhancement].
- o Regulatory update - 5GHZ restriction in Taiwan.

### Fixes and Known Issues in MSP Agent v7.03.58:

"For MSP release notes, see Support Central and refer to the Release Notes document for the latest MSP release."

- Mobility Services Platform 3.3.1 Release Notes  
<https://support.symbol.com/support/search.do?cmd=displayKC&docType=kc&externalId=12920&sliceId=&dialogID=209356172&stateId=1%200%20209352171>

### Features/Fixes in WWAN

- o SPR 19819: Included updated CDMA RIL v3.25.

### MC95x8 Specific Changes /Known Issues:

- Added Support for CMI display panels.
- Monitor version 01.24.0000
- SPR 19652 Fix: Cannot make dial out serial connections on COM1 using RAS API's.
- SPR 18352 Fix: Audio pop in speaker when recording wav file. (Minimal sound heard).
- SPR 19361 Fix: 21-116368-01 R headset quick disconnect adapter has intermittent static and disconnection issues.
- SPR 20197 Fix: Need 0-9 keys mapped to F1-F10 by orange key on MC95 52 key unit.
- CPLD version 5.1 for Rev D (CMI display) hardware.

#### Known Issues:

- o Unable to upload APF files in to MSP server for MC95xx products.  
 Workaround: MC959x RevC/RevD OS size has been increased to 128MB OS. So the size of the APF file becomes 128MB. IIS has this limitation. User need to keep the APF file in "Program Files\Motorola MSP\PackagesToInstall" directory directly.
- o While in Private call of Team Express user is able to hear key press events.

*Workaround:* Start>Settings>Control Panel>Volume&Sounds>Uncheck 'Key clicks'. After that the noise stops being heard.

o Default Team Express Private call key is not mapped to any key. User must configure the key before starting the session.

### Known issues in Platform:

- After team express installation, device takes 3 minutes to suspend.
- "Datawedge" will not be installed on Cleanboot hence Titanium Screen would not have Datawedge entry for all terminals. However, Datawedge.cab is available in \Windows folder for the user to install. After installation, user can find Datawedge shortcut on the Titanium screen.
- If the user wants to install DataWedge at Clean Boot, then the following registry key should be put in .reg file and placed in \Application folder and then the terminal should be clean booted.  
[HKEY\_LOCAL\_MACHINE\SOFTWARE\Motorola\DWStartUp]  
"DontInstallOnStartUp"=dword:00000000
- "GettingStarted" entry has been removed from the Titanium screen. After a cold/warm boot, "GettingStarted" icon position will be moved lower in Start->Programs.

### Known issues in the Windows Mobile Products:

- By default Input panel applet is not displayed in Start->Settings->Personal page due to a known issue from Microsoft wherein the user will not be able to close the Input panel applet. As a workaround if enabled, the applet can be closed using the "OK" button on the hard keyboard. Remove the below registry entry and reboot, to display the "Input" applet under Settings\Personal page.  
"Redirect"=""  
which is present in the following section:  
[HKEY\_LOCAL\_MACHINE\ControlPanel\Input]
- When switching between Control Panel Applets, the previously opened Applet's title is shown on the currently opened applet.

### Contents

1. 95x8w65HenUL044104.zip - UpdateLoader Package.
2. 95x8w65HenAB044104.APF - AirBeam package.
3. IMPORTANT NOTES FOR Upgrading & Downgrading MC959x\_RevD.doc

### Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC95x8	Windows Mobile 6.5 Professional

### Installation Requirements

MC95X8 device must contain a released version of WM6.5 Software

### Installation Instructions

#### **IMPORTANT NOTES FOR Updating and Downgrading MC959x Device to/from BSP41 (v4.41.04) RevD**

Upgrading to v4.41.04 RevD SW:

- If your device is running BSP27 (v2.27.08) / BSP37 (v3.37.02)/BSP41 (v4.41.03) Windows Mobile 6.5, you can simply use the BSP41 (RevD SW v4.41.04) Update Loader package to update from BSP27/BSP35/BSP41 to BSP41 (v4.41.04).
- If your device is running BSP19 (v1.19.11), you must first update your device to the released version of BSP27 (v2.27.08). Once the device is running BSP27, you can then perform the update to BSP41 (v4.41.04).

## Downgrading to BSP37/BSP27/BSP19:

- **If your device is having CPLD 5.02 then it is a Old Main Board device having CMI display. This device is not allowed to downgrade to 04.41.03 or earlier Image.**

*(Go to System Info Applet on the device to find the CPLD Version : Start->Settings->System->"System Info" Applet->"HW Version". For OLD Main Board CPLD ver:5.02)*

- **If your device was manufactured before Dec 1,2012 and your device has 256MB RAM/LG Display , you are only permitted to downgrade to BSP37(v3.37.02)/BSP27(v2.27.08)**

*(Go to System Info Applet on the device to find the RAM size: Start->Settings->System->"System Info" Applet->"Misc" Page)*

*(Go to System Info Applet on the device to find the Display ID: Start->Settings->System->"System Info" Applet->"Display". For CMI->PJ037PD,For LG->LH370V01)*

- **If your device was manufactured on or after Dec 1,2012 and your device has CMI Display, you WOULD NOT be able to Downgrade to BSP37(v3.37.02) / BSP27 (v2.27.08) / BSP19 (1.19.11)**

*(DO NOT Downgrade MC95xx devices built on or after Dec 2012 with the new CMI display to BSP37 (v3.37.02), BSP27 (v2.27.08), BSP19 (1.19.11) since these BSPs do not have support for CMI display)*

*(Go to System Info Applet on the device to find the Display ID: Start->Settings->System->"System Info" Applet->"Display". For CMI->PJ037PD,For LG->LH370V01)*

- **If your device has 128MB RAM and running with BSP41 (v4.41.03), you are permitted to downgrade to BSP37(v3.37.02), BSP27 (v2.27.08) and BSP19 (v1.19.11). However, if you want to downgrade to BSP19 (v1.19.11), you must first downgrade to BSP27 (v2.27.08) before performing the downgrade to BSP19 (v1.19.11).**

*(Go to System Info Applet on the device to find the RAM size: Start->Settings->System->"System Info" Applet->"Misc" Page)*

## Part Number and Release Date

18 Dec 2013

1. 95x8w65HenUL044104.zip
2. 95x8w65HenAB044104.APF