



MC2100 OPERATING SYSTEM FOR PROFESSIONAL REV D - BSP 04.34.0122 - LOCALIZATION RELEASE NOTES

INTRODUCTION

From the sales floor to the backroom, the Symbol MC2100 mobile computer has what it takes to affordably automate the capture of inventory data right at the point of work. Leveraging Symbol's Mobility Platform Architecture 2.0, the MC2100 offers plenty of processing power, industry-leading data capture capabilities, rugged design, superior ergonomics, flexible data capture options, plus centralized management. Support for Symbol's RhoElements application development platform allows you to create cross-platform applications that work on different mobile computers with different operating systems. MC2100 is available in Wireless LAN (802.11b/g/n) and Batch configuration

DESCRIPTION

General Enhancements in 04.34.0122

ReBranded Components:

- Fusion - Version FUSION_X_2_02.0.0.024R(FCC Compliant)
- DataWedge - Verison 3.7.16
- RTLog Manager
- Splash Screen
- emScript v1.3.5, CaptureDump
- PTT/Team Express v1.1.71.0000 is integrated
- Asset Tracker Lite v1.0 is integrated
- RhoElements Framework v02.02.01.12.00
- CtlPanel v4.2.3
- RhoElement Basic Browser v2.0(WLAN configuration only)

SPR Fixes



- SPR26412 - Improvement has been made in Scanner Decoder Performance.
- SPR26357 - Resolved an issue wherein MC21 Laser Beam width was Unstable.
- SPR25400 - Resolved an issue wherein Picklist Mode was not accurate.
- SPR23867 - Resolved an issue wherein Dial Up Reconnection was not happening after device suspend resume.
- SPR25065 - Resolved an Issue wherein entering the https into basic browser app was failing to navigate to the address.

CONTENTS

1	2100c60BcpOS043422.hex	OS Hex file v04.34.22
2	2100c60BctOS043422.hex	OS Hex file v04.34.22
3	2100c60BdeOS043422.hex	OS Hex file v04.34.22
4	2100c60BfrOS043422.hex	OS Hex file v04.34.22
5	2100c60BitOS043422.hex	OS Hex file v04.34.22
6	2100c60BjpOS043422.hex	OS Hex file v04.34.22
7	2100c60BkoOS043422.hex	OS Hex file v04.34.22
8	2100c60BpbOS043422.hex	OS Hex file v04.34.22
9	2100c60BsiOS043422.hex	OS Hex file v04.34.22
10	2100c60BcpAB043422.APF	AirBeam Package Without Clean App v04.34.22
11	2100c60BctAB043422.APF	AirBeam Package Without Clean App v04.34.22
12	2100c60BdeAB043422.APF	AirBeam Package Without Clean App v04.34.22



13	2100c60BfrAB043422.APF	AirBeam Package Without Clean App v04.34.22
14	2100c60BitAB043422.APF	AirBeam Package Without Clean App v04.34.22
15	2100c60BjpAB043422.APF	AirBeam Package Without Clean App v04.34.22
16	2100c60BkoAB043422.APF	AirBeam Package Without Clean App v04.34.22
17	2100c60BpbAB043422.APF	AirBeam Package Without Clean App v04.34.22
18	2100c60BsiAB043422.APF	AirBeam Package Without Clean App v04.34.22
19	2100c60BcpUP043422.zip	OsUpdate Package v04.34.22
20	2100c60BctUP043422.zip	OsUpdate Package v04.34.22
21	2100c60BdeUP043422.zip	OsUpdate Package v04.34.22
22	2100c60BfrUP043422.zip	OsUpdate Package v04.34.22
23	2100c60BitUP043422.zip	OsUpdate Package v04.34.22
24	2100c60BjpUP043422.zip	OsUpdate Package v04.34.22
25	2100c60BkoUP043422.zip	OsUpdate Package v04.34.22
26	2100c60BpbUP043422.zip	OsUpdate Package v04.34.22
27	2100c60BsiUP043422.zip	OsUpdate Package v04.34.22

DEVICE COMPATIBILITY

This software release has been approved for use with the following Symbol devices.

Device	Operating System
--------	------------------



MC2100	Windows CE 6.0 Professional
MC2180	Windows CE 6.0 Professional

INSTALLATION REQUIREMENTS

MC2100 device must contain a released version of CE 6.0 Professional Software.

INSTALLATION INSTRUCTIONS

Update through \Storage Card

- Unzip 2100c60BxxUP043422.zip file and copy its contents (**OSUpdate** folder) to the root folder on SD card.
- Insert the SD card in the device to be updated.
- Place the device to be updated on A/C power supply.
- Run **2100c60Bxx_SD** shortcut from **\Storage Card\OSUpdate** folder to start the update process.

Update through \Application

- Unzip 2100c60BxxUP043422.zip file and copy its content (**OSUpdate** folder) to the **\Application** folder.
- Place the device to be updated on A/C power supply.
- Run **2100c60Bxx_App** shortcut from **\Application\OSUpdate** folder to start the update process.

Notes:

- Keep the device in AC Power during the update process.
- Updating through Temp folder is not supported in MC2100 due to RAM space constraints.
- While using Application partition update method, Application data will be kept intact and OSUpdate folder will also remain after completing the OS Update process.

PART NUMBER AND RELEASE DATE

2100c60BcpOS043422

2100c60BctOS043422



2100c60BdeOS043422

2100c60BfrOS043422

2100c60BitOS043422

2100c60BjpOS043422

2100c60BkoOS043422

2100c60BpbOS043422

2100c60BsiOS043422

2100c60BcpAB043422

2100c60BctAB043422

2100c60BdeAB043422

2100c60BfrAB043422

2100c60BitAB043422

2100c60BjpAB043422

2100c60BkoAB043422

2100c60BpbAB043422

2100c60BsiAB043422

2100c60BcpUP043422

2100c60BctUP043422

2100c60BdeUP043422

2100c60BfrUP043422

2100c60BitUP043422

2100c60BjpUP043422



2100c60BkoUP043422

2100c60BpbUP043422

2100c60BsiUP043422

October 03, 2016