

Xplore Technologies Software Release Note

Name	Sierra Wireless LTE WAN Driver and Skylight Connection Manager
File Name	WWAN_Win7_EM7305_v4382.zip WWAN_Win7_EM7355_v4382.zip
Release Date	May 9, 2016
This Version	Driver 6.19.4382 Skylight 6.0.4378
Replaces Version	All previous versions
Intended Product	iX101B1 (Bobcat)
File Size	250 MB
Supported Operating System	Windows 7

Fixes in this Release

- Updated firmware images to latest 05.05.xx.xx
- Automatic firmware switching enhancements
- Prevent Selective Suspend when NMEA enabled
- Auto-connect logic enhancements
- Improved stability during power management events
- Fixed OTA APN update on Sprint

What's New in this Release

N/A

Known Issues and Limitations

N/A

Installation and Configuration Instructions

To install Driver 4382 and CM 4378, perform the following steps:

- 1. Download the appropriate update and save to the directory location of your choice.
- 2. Unzip the file to a location on your local drive.
- 3. Double-click the driver installer (Generic73x5DriverSetup.exe) and follow the prompts.
- 4. Double-click the application installer (Skylight_B4378.exe) and follow the prompts (CM required for Windows 7).

Licensing

Refer to your applicable end-user licensing agreement for usage terms.