

7528_WEH65Cab_3.4.44217

Software Release Notice

12/21/2016

Release Date: 2016.12.21

Release Images: Part

Released @ Iteration 1

7528_WM65_PRO_CHS_ADDON_3.4.44217 [1102025]
7528_WM65_PRO_CHT_ADDON_3.4.44217 [1102021]
7528_WM65_PRO_ESN_ADDON_3.4.44217 [1102019]
7528_WM65_PRO_FRA_ADDON_3.4.44217 [1102016]
7528_WM65_PRO_GER_ADDON_3.4.44217 [1102018]
7528_WM65_PRO_ITA_ADDON_3.4.44217 [1102017]
7528_WM65_PRO_JPN_ADDON_3.4.44217 [1102022]
7528_WM65_PRO_KOR_ADDON_3.4.44217 [1102023]
7528_WM65_PRO_WWE_ADDON_3.4.44217 [1102015]

Release History:

7528_WM65_PRO_CHT_ADDON_3.3.43941 (7528.1248.1 Released@2016-05-31)
7528_WM65_PRO_CHT_ADDON_3.2.43808 (7528.1244.2 Released@2016-03-30)
7528_WM65_PRO_CHT_ADDON_3.1.43786 (7528.1242.2 Released@2016-03-23)
7528_WM65_PRO_CHT_ADDON_3.43303 (7528.1229.1 Released@2016-01-29)
7528_WM65_PRO_CHT_ADDON_2.5.43052 (7528.1221.1 Released@2015-07-23)
7528_WM65_PRO_CHT_ADDON_2.4.42930 (7528.1215.2 Released@2015-04-29)
7528_WM65_PRO_CHT_ADDON_2.3.42074 (7528.1196.1 Released@2014-12-19)
7528_WM65_PRO_CHT_ADDON_2.2.40449 (7528.1175.3 Released@2014-07-10)
7528_WM65_PRO_ESN_2.2.39962 (7528.1175.1 Released@2014-06-02)
7528_WM65_PRO_CHT_ADDON_2.38436 (7528.1167.2 Released@2014-02-25)
7528_WM65_PRO_ESN_2.38323 (7528.1167.1 Released@2014-02-25)
7528_WM65_PRO_ITA_ADDON_1.37641 (7528.1152.4 Released@2014-01-14)
7528_WM65_PRO_ESN_1.37207 (7528.1152.3 Released@2014-01-15)

SOFTWARE CHANGES

This section provides a list of software changes made since the last Release.

0

check-in(s), that is/are italic, has/have configuration or parameter changes.

Iteration 1

Existing Components

7528 Release/8 @43770 -> QA/9 @44202

(7528WEH6Package/7528WEH6/7528,7528WEH6Package/7528WEH6Cab/7528)

[SCR-38257: Update power table to comply with FCC 5Ghz rule.](#)

- [CI-43949: Update WLAN power table to comply with FCC 5GHz regulation.](#)

[SCR-38291: WAP4 will not automatically suspend if Fusion Profile Roaming is enabled.](#)

- [CI-43751: Downward integrate CI-43737 from 7528 QA/8 to Main](#)

[SCR-38368: 7528 wap4 Onboard GPS receiver does not provide accurate NMEA data](#)

- [CI-43845: Update the TI_1283 GPS firmware.](#)

[SCR-38410: Cannot use external BT GPS device on the WAP4](#)

[- CI-44183: Allow external GPS devices to use the GPS intermediate driver \(GPSID\).](#)

WinCECommon Release/20 @43772 -> QA/22 @44203

(7528WEH6Package/7528WEH6/WinCECommon,7528WEH6Package/7528WEH6Cab/WinCECommon)

[SCR-38366: TekTerm doesn't resize when VC70 SIP is opened.](#)

[- CI-43763: Allowed landscape window to resize when SIP is up.](#)

[- CI-43831: Restored full screen when XAMLIM SIP comes down](#)

[- CI-43853: Applied SIP resizing only to main window and not to other windows.](#)

[SCR-38399: Battery Health Status Indicator for 7528 WAP4 Workabout Pro4](#)

[- CI-44175: Update Battery Health applet to detect and display Unknown batteries.](#)

WM600 Release/8 @42988 -> QA/9 @44204

(7528WEH6Package/7528WEH6/WM600,7528WEH6Package/7528WEH6Cab/WM600)

[SCR-38410: Cannot use external BT GPS device on the WAP4](#)

[- CI-44184: Allow external GPS devices to use the GPS intermediate driver \(GPSID\).](#)

This document is proprietary and as such cannot be disclosed, used, copied, or transmitted without prior consent of Psion Inc.

Copyright Psion Inc. 2016.