



Xplore Technologies Software Release Note

Name	Sierra Wireless LTE WAN Driver and Skylight Connection Manager
File Name	WWAN_W81-W10_EM7305_v4382.zip WWAN_W81-W10_EM7355_v4382.zip
Release Date	May 09, 2016
This Version	Driver 6.19.4382 Skylight 6.0.4378
Replaces Version	All previous versions
Intended Product	iX101B1 (Bobcat)
File Size	250 MB
Supported Operating System	Windows 8.1 Windows 10

Fixes in this Release

- Updated firmware images to latest 05.05.xx.xx
- Automatic firmware switching enhancements
- Prevent Selective Suspend when NMEA enabled
- Auto-connect logic enhancements
- Improved stability during power management events
- Fixed OTA APN update on Sprint

What's New in this Release

- N/A

Known Issues and Limitations

- N/A

Installation and Configuration Instructions

To install Driver 4382 and CM 4378, perform the following steps:

1. Download the appropriate update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Double-click the driver installer (Generic73x5DriverSetup.exe) and follow the prompts.
4. Double-click the application installer (Skylight_B4378.exe) and follow the prompts (optional for Windows 8.1 and 10).

Licensing

Refer to your applicable end-user licensing agreement for usage terms.