



# MC9100 OPERATING SYSTEM WM OEM 41 AND CE OEM 32 RELEASE NOTES

## INTRODUCTION

Unable to lock the function state for MC9190 WM/CE

## DESCRIPTION

Using this patch you will be able to lock function state by double press function key.

## CONTENTS

- 23705.cab - for worldwide WM6.5
- 23705\_woBoot.cab - for worldwide WM6.5
- 23960.cab - for worldwide CE6.0
- 23960\_woBoot.cab - for worldwide CE6.0
- 23960\_KoreanOS.cab – for Korean CE6.0 image
- 23960\_KoreanOS\_woBoot.cab - for Korean CE6.0 image

## DEVICE COMPATIBILITY

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC9190	Windows Mobile 6.5 OEM 41 and CE 6.0 OEM32 worldwide + Korean Localized Image

## INSTALLATION REQUIREMENTS

n/a

## INSTALLATION INSTRUCTIONS

\*\*\*.CAB : Copy the file to the device and double click on it. Confirm for all overwrite suggestions. Device will be rebooted automatically when installation completed.

\*\*\*\_woBoot.CAB: Copy the file to the device and double click on it. Confirm for all overwrite suggestions. Cold boot the device manually after the installation completed.

## PART NUMBER AND RELEASE DATE

July 8, 2013



**Notes:**

To have the Function lock enabled the following registry should be applied:

```
[HKEY_LOCAL_MACHINE\Hardware\DEVICEMAP\KEYBD]
```

```
"FuncLockState"=dword:00000000
```

The patch has known issue for CE6.0: when Function locked, Shift locked icon displayed as well. The issue is cosmetic only, the device works according to Function lock rules.