



MC2100 OPERATING SYSTEM FOR CORE REV D - BSP 04.34.0120 – LOCALIZATION

INTRODUCTION

From the sales floor to the backroom, the Symbol MC2100 mobile computer has what it takes to affordably automate the capture of inventory data right at the point of work. Leveraging Symbol's Mobility Platform Architecture 2.0, the MC2100 offers plenty of processing power, industry-leading data capture capabilities, rugged design, superior ergonomics, flexible data capture options, plus centralized management. Support for Symbol's RhoElements application development platform allows you to create cross-platform applications that work on different mobile computers with different operating systems. MC2100 is available in Wireless LAN (802.11b/g/n) and Batch configuration

DESCRIPTION

General Enhancements in 04.34.0120

ReBranded Components:

- Fusion - Version FUSION_X_2_02.0.0.024R(FCC Compliant)
- DataWedge - Verison 3.7.16
- RTLog Manager
- Splash Screen
- emScript v1.3.5, CaptureDump
- PTT/Team Express v1.1.71.0000 is integrated
- Asset Tracker Lite v1.0 is integrated
- RhoElements Framework v02.02.01.12.00
- CtlPanel v4.2.3
- RhoElement Basic Browser v2.0(WLAN configuration only)



SPR Fixes

- SPR26412 - Improvement has been made in Scanner Decoder Performance.
- SPR26357 - Resolved an issue wherein MC21 Laser Beam width was Unstable.
- SPR25400 - Resolved an issue wherein Picklist Mode was not accurate.
- SPR23867 - Resolved an issue wherein Dial Up Reconnection was not happening after device suspend resume.
- SPR25065 - Resolved an Issue wherein entering the https into basic browser app was failing to navigate to the address.

CONTENTS

1	2100c60AcpUP043420	OsUpdate Package v04.34.20
2	2100c60ActUP043420	OsUpdate Package v04.34.20
3	2100c60AdeUP043420	OsUpdate Package v04.34.20
4	2100c60AfrUP043420	OsUpdate Package v04.34.20
5	2100c60AitUP043420	OsUpdate Package v04.34.20
6	2100c60AjpUP043420	OsUpdate Package v04.34.20
7	2100c60AkoUP043420	OsUpdate Package v04.34.20
8	2100c60ApbUP043420	OsUpdate Package v04.34.20
9	2100c60AsiUP043420	OsUpdate Package v04.34.20
10	2100c60AcpAB043420	AirBeam Package without Clean App v04.34.20
11	2100c60AcpOS043420	OS Hex file v04.34.20
12	2100c60ActAB043420	AirBeam Package without Clean App v04.34.20



13	2100c60ActOS043420	OS Hex file v04.34.20
14	2100c60AdeAB043420	AirBeam Package without Clean App v04.34.20
15	2100c60AdeOS043420	OS Hex file v04.34.20
16	2100c60AfrAB043420	AirBeam Package without Clean App v04.34.20
17	2100c60AfrOS043420	OS Hex file v04.34.20
18	2100c60AitAB043420	AirBeam Package without Clean App v04.34.20
19	2100c60AitOS043420	OS Hex file v04.34.20
20	2100c60AjpAB043420	AirBeam Package without Clean App v04.34.20
21	2100c60AjpOS043420	OS Hex file v04.34.20
22	2100c60AkoAB043420	AirBeam Package without Clean App v04.34.20
23	2100c60AkoOS043420	OS Hex file v04.34.20
24	2100c60ApbAB043420	AirBeam Package without Clean App v04.34.20
25	2100c60ApbOS043420	OS Hex file v04.34.20
26	2100c60AsiAB043420	AirBeam Package without Clean App v04.34.20
27	2100c60AsiOS043420	OS Hex file v04.34.20

DEVICE COMPATIBILITY

This software release has been approved for use with the following Symbol devices.



Device	Operating System
MC2100	Windows CE 6.0 Core
MC2180	Windows CE 6.0 Core

INSTALLATION REQUIREMENTS

MC2100 device must contain a released version of CE 6.0 Core Software.

INSTALLATION INSTRUCTIONS

Update through \Storage Card

- Unzip 2100c60AxxUP043420.zip file and copy its contents (**OSUpdate** folder) to the root folder on SD card.
- Insert the SD card in the device to be updated.
- Place the device to be updated on A/C power supply.
- Run **2100c60Axx_SD** shortcut from **\Storage Card\OSUpdate** folder to start the update process.

Update through \Application

- Unzip 2100c60AxxUP043420.zip file and copy its content (**OSUpdate** folder) to the **\Application** folder.
- Place the device to be updated on A/C power supply.
- Run **2100c60Axx_App** shortcut from **\Application\OSUpdate** folder to start the update process.

Notes:

- Keep the device in AC Power during the update process.
- Updating through Temp folder is not supported in MC2100 due to RAM space constraints.
- While using Application partition update method, Application data will be kept intact and OSUpdate folder will also remain after completing the OS Update process.

PART NUMBER AND RELEASE DATE

2100c60AcpAB043420

2100c60ActAB043420



2100c60AdeAB043420
2100c60AfrAB043420
2100c60AitAB043420
2100c60AjpAB043420
2100c60AkoAB043420
2100c60ApbAB043420
2100c60AsiAB043420

September 21, 2016