

MT20X0 LASER DECODE STOP SPR19275 HOTFIX RELEASE NOTES, VERSION 1.0.0.3

DESCRIPTION

This hotfix fixes the issue that on MT 20x0 with laser scan engine, the scan beam intermittently comes on but stops decoding.

DEVICE COMPATIBILITY

MT2070 (with laser scan engine)

MT2090 (with laser scan engine)

RELEASE NOTES

VERSION: 1.0.0.3

The hotfix fixes the issue that on MT 20x0 with laser scan engine, the scan beam intermittently comes on but stops decoding.

CamScanPDD1D.dll – 1.0.0.3

COMPONENTS

The installed file should be in the following folder on the scanner.

| Component | Location |
|------------------|------------|
| CamScanPDD1D.dll | \Platform\ |
| CamScanPDD1D.cpy | \Platform\ |

INSTALLATION

The following is the procedure to apply the Hotfix. It is assumed that the ActiveSync installed on the PC.

- 1) ActiveSync the scanner to a PC;
- 2) Open up the “Platform” folder on the device using “Explore” on ActiveSync;
- 3) Copy the CamScanPDD1D.dll file and the CamScanPDD1D.cpy to “Platform” folder:

4) Cold boot the scanner (by press and hold scan trigger and '2' key. Wait for screen going black the 2nd time and release the trigger and key. Or, just remove the battery and reinsert it to cold boot.)

The scanner should boot up with the Hotfix applied.