



# WT4000 Connector Shroud Installation Instructions

## Connector Shroud Assembly

1. Remove cable from WT4000, if required.
2. Align the cable connector with the connector shroud bottom housing. Ensure that the disconnect button on the connector faces up.



3. Place the cable connector into the shroud bottom housing as shown.



4. Press the top housing into the bottom housing. The housings will snap together.


5. Plug the cable connector into the WT4000 connector.

## Disconnecting the Cable from the WT4000

- ✓ **NOTE** Follow the instructions below when disconnecting the cable connector and shroud from the WT4000. Once the shroud is installed on the connector, do not disassemble the shroud by prying it apart.

Turn the WT4000 over to expose the top housing of the shroud.

Push the tip of a ball-point pen through the hole in the connector shroud top housing. The connector disengages from the WT4000.



72-113478-02 Revision A - December 2014

Zebra Technologies Corporation  
Lincolnshire, IL U.S.A.