

---

# Release Notes Driver package for OS V01.00.14 with BIOS V-13 for ET50/ET55 Windows 10

## Contents

---

[Description](#)

[Device Compatibility](#)

[Component Contents](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Downloadable Software included in this Release](#)

## Description

---

Updated release for ET55/ET50 Windows 10 includes the following changes:

- Updated Redstone 2 [RS2] driver Release from Microsoft [ Build 15063].
- Added Broadcom Wifi driver 5.93.102.22 in the component folder. Driver 5.93.102.22 is enabled by default.
- Updated BIOS version -013 to support new audio codec, updated camera I2C Address and new Memory Die shrink.

Note : Current BIOS v-013 is backward compatible with previous hardware [MFD May 2017 or earlier] however, BIOS v-013 can not be downgraded to previous BIOS versions. BIOS v-013 is programmed at factory to devices manufactured after 1st of June 2017. [MFD June 2017 or later].

## Device Compatibility

---

List any exceptions or hardware change that is not support by this software release.

| Device | Operating System                  |
|--------|-----------------------------------|
| ET50   | Windows 10 Enterprise             |
| ET55   | Windows 10 Enterprise             |
| ET50   | Windows Embedded 8.1 Industry Pro |
| ET55   | Windows Embedded 8.1 Industry Pro |

## Component Contents

---

| Component                       | Version                 |
|---------------------------------|-------------------------|
| <b>Windows 10 Enterprise</b>    | OS Build 15063          |
| <b>Insyde Baytrail Bios</b>     | V5.04.48.0060.          |
| <b>Intel Baytrail Bios FRC</b>  | V1.9.0                  |
| <b>Intel Baytrail TXE FW</b>    | V1.2.1.1153.            |
| <b>Intel Baytrail Drivers</b>   | VWW34_2015.             |
| <b>Huawei LTE/3G</b>            | V5.0(11.100.00.02.1818) |
| <b>Sierra Wireless modem FW</b> | V4.3.1.6                |
| <b>WIFI</b>                     | V5.93.102.22.           |
| <b>BT</b>                       | V12.0.0.9190.           |
| <b>GPS</b>                      | V20.22.405.18.          |
| <b>NFC</b>                      | V6.5.9.0.               |
| <b>3G Modem</b>                 | V10.0.14393.0.          |
| <b>ULPMC</b>                    | ULPMC_64_09             |
| <b>BIOS</b>                     | V-013                   |

## Installation Requirements

---

ET5X device must contain a released version of Windows Embedded 8.1 Industry Pro / Windows 10 Enterprise.

## Installation Instructions

---

- Please see MDT\_HowToWindows10.pdf which is part of WIN10-ZEBRA-R1.0-014-X64-Components.zip for MDT instructions.

## Downloadable Software Included in this Release

---

| Filename   | Description  |
|--|--|
| <b>WIN10-ZEBRA-R1.0-014-X64-DeferWU2-Components_bios13.zip</b> | Driver components corresponding to OS01.00.14 of ET50/ET55 Windows 10 along with the documentation on MDT and SCCM deployment. |
| <b>WIN10-ZEBRA-R1.0-014-X64- DeferWU2-DeploymentShare.zip</b>  | MDT Deployment share corresponding to OS01.00.14 of ET50/ET55 Windows 10   |
|  |  |

Last Revised: <01-29-2018>

