



Xplore Technologies Software Release Note

Name	Sierra Wireless Driver Package for Windows 8.1
File Name	Sierra_Wireless_EM7305_Win8.1_64bit_6.11.4262.0009.zip Sierra_Wireless_EM7355_Win8.1_64bit_6.11.4262.0009.zip
Release Date	May 12, 2015
This Version	6.11.4262.0009 (B4262)
Replaces Version	All previous versions
Intended Users	Motion CL920, R12, and C5m/F5m users
Intended Product	Motion CL920, R12, C5m/F5m Tablet PCs ONLY
File Size	213 MB
Supported Operating System	Windows 8.1 (64-bit)

Fixes in this Release

- Fixed issue of not attached to network when turning off and on device with auto connect enabled
- Yellow bang recovery logic enhancement
- Auto-connect logic enhancement to work around MS Win7 missing connection complete notification when signal strength is weak
- Auto connect is now working correctly on Verizon image after system suspend/resume
- Image switching to Generic FW not performed if SIM information is not available

What's New In This Release

- None

Known Issues and Limitations

- User should load their preferred network provider before inserting their SIM

Installation and Configuration Instructions

To install Wireless drivers, perform the following steps:

1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Double-click the installer (.exe) and follow the prompts.

Licensing

Refer to your applicable end-user licensing agreement for usage terms.