Release Notes – MC32N0 CE 7.0 - No scan beam comes out in MobiControl stage after 6-7 seconds - SPR32168

Contents

Introduction

Description

Contents

Device Compatibility

Installation Requirements

Installation Instructions

Release Date

Introduction

SPR32168 - On latest OS image with mobi control stage scan beam does not come out after sometime

Description

On mobi control stage scan beam does not come on BSP v00.57.12/v10.57.12

Resolve an issue wherein device scan beam does not come out in mobi control stage.

Contents

SPR32168_MC32_C7_v005712_en_WB_v1_0.cab (HotFix package with auto Warm boot)

SPR32168_MC32_C7_v005712_en_NB_v1_0.cab (HotFix package without auto Warm boot)

Device Compatibility

This HotFix Package software release has been approved for use with the following Zebra devices.

Device	Operating System	BSP Version
MC32N0	CE 7.0	v00.57.12/v10.57.12

Installation Requirements

This SW is intended for MC32N0 CE7 devices with OS v00.57.12/v10.57.12

Installation Instructions

For Normal installation of the PATCH:

- 1. Copy "SPR32168_MC32_C7_v005712_en_WB_v1_0.cab" file to the application folder/SD card on the device by using Microsoft Active Sync or Mobile Device Center.
- 2. Navigate on the device to the application folder/SD card.
- 3. Deploy the solution by tapping on the "SPR32168_MC32_C7_v005712_en_WB_v1_0.cab" file.
- 4. After successful deployment of the "SPR32168_MC32_C7_v005712_en_WB_v1_0.cab" file, device will do an automatic warm boot.

For MSP or REMOTE installation of the PATCH:

- Set up MDM (MSP, Soti, Airwatch, etc..) to send
 "SPR32168_MC32_C7_v005712_en_NB_v1_0.cab" file to the application folder of the device.
- To deploy the solution, setup in MDM to install the cab file "SPR32168_MC32_C7_v005712_en_NB_v1_0.cab" file.
- 3. Changes will take effect after a manual reboot of the terminal or if MDM reboots device.

Release Date

May, 2017