Release Notes - WT41N0 CE7 Rev B - 02.46.02 - Localization

Introduction

Description

Contents

Device Compatibility

<u>Installation Requirements</u>

<u>Installation Instructions</u>

Part Number and Release Date

1 Introduction

WT41N0 is the Next Generation version of earlier wearable series of mobile computer WT4090. WT41N0 arm's your workers with all new advanced real-time hands-free mobile computing. This rugged mobile computing device with 802.11 a/b/g/n will allow you to achieve maximum error-proof productivity, operational efficiency and accuracy through voice compatibility for streamlined warehouse and package handling functions.

2 Description

- 1. Operating System: CE7.0.
- 2. QFE: April 2014
- 3. CPU OMAP4430 ES 2.3.

- 4. Fusion Radio SW X2.01_89R.
- 5. External Agent 02.54
- 6. Wavelink TE 7.3.192
- 7. Bluetooth StoneStreet Stack 2.1.1 Build 28004

3 Enhancements

4 SPRs fixed

- SPR25142 Resolved an issue whereby CE7 RDP Client GUI is not sized correctly
- SPR25155 Resolved an issue whereby Time Service is not working as expected
- SPR25366 Resolved an issue whereby IE7 Kiosk mode, URL bar was accessible when pressing TAB key
- SPR24941 Resolved an issue whereby SSL socket does not correctly close when Alert (close_notify) is sent on CE7 device
- SPR24629 Integrated Wideband Audio Support for WT41N0
- SPR25083 Added support to turn off Microphone.

By default Mic is enabled, set below registries to disable it.

```
[HKEY_LOCAL_MACHINE\Drivers\BuiltIn\TWA]
"MuteMic"=dword:00000001
```

• SPR24367 – Added three states support for Orange and Grey keys i.e. Enable, Lock and Disable.

By default Feature is disabled, set below registries to enable it.

```
[HKEY_LOCAL_MACHINE\HARDWARE\DEVICEMAP\KEYBD] "DoOrangeGrey"=dword:00000001
```

- SPR25569 Resolved and issue whereby Bluetooth connection is severed and requires a reboot to re-establish after time running in a freezer.
- SPR25976 Resolved and issue whereby Telnet disconnects on WT41 on CISCO infratucture

5 Notes

• While streaming video files from Web for a long hours, it is recommended to change the default Temporary Internet Files registry path to the following.

 $[HKEY_CURRENT_USER\Software\Microsoft\Windows\Current\Version\Explorer\Shell\Folders]$

"Cache"="\\Application\\Temporary Internet Files"

• RCM Trigger Notification Support has been added via the following registry

By default RCM trigger Notification is disabled. Please set below registries to enable it. [HKEY_LOCAL_MACHINE\Drivers\BuiltIn\BarCodeReader\Settings] "TriggerEventEnable"=dword:1

 $[HKEY_LOCAL_MACHINE \ Drivers \ Built In \ BarCode Reader \ Configurations \ SE965 \ Settings] \\ "Trigger Event Enable" = dword: 1$

 $[HKEY_LOCAL_MACHINE \ Drivers \ BuiltIn \ BarcodeReaderBT \ Settings] \\ "TriggerEventEnable" = dword: 1$

- Included Firmware Update utility (\Windows\FirmwareUpdate\FirmwareUpdate.exe) for upgarding RS507 firmware. Please select view all file option to use the utility
- Included Scanner Log utility (\Windows\ScannerLog\ScannerLog.exe) to capture RS507 Scanner logs. Please select view all file option to use the utility
- Batteryhealth application is part of the OS image. In order to use this Utility user needs to go and double click on Start->Program->BatteryHealth to install the cab file.

6 Contents

- 1 41X0BcpUC024602.zip OS Update Package v02.46.02 with CleanAppl for Touch and Non-Touch terminals
- 2 41X0BcpUP024602.zip OS Update Package v02.46.02 without CleanAppl for Touch and Non-Touch terminals
- 3 41X0BctUC024602.zip OS Update Package v02.46.02 with CleanAppl for Touch and Non-Touch terminals
- 4 41X0BctUP024602.zip OS Update Package v02.46.02 without CleanAppl for Touch and Non-Touch terminals
- 5 41X0BdeUC024602.zip OS Update Package v02.46.02 with CleanAppl for Touch and Non-Touch terminals
- 6 41X0BdeUP024602.zip OS Update Package v02.46.02 without CleanAppl for Touch and Non-Touch terminals
- 7 41X0BfrUC024602.zip OS Update Package v02.46.02 with CleanAppl for Touch and Non-Touch terminals
- 8 41X0BfrUP024602.zip OS Update Package v02.46.02 without CleanAppl for Touch and Non-Touch terminals
- 9 41X0BitUC024602.zip OS Update Package v02.46.02 with CleanAppl for Touch and Non-Touch terminals
- 10 41X0BitUP024602.zip OS Update Package v02.46.02 without CleanAppl for Touch and Non-Touch terminals
- 11 41X0BjpUC024602.zip OS Update Package v02.46.02 with CleanAppl for Touch and Non-Touch terminals

- 12 41X0BjpUP024602.zip OS Update Package v02.46.02 without CleanAppl for Touch and Non-Touch terminals
- 13 41X0BkoUC024602.zip OS Update Package v02.46.02 with CleanAppl for Touch and Non-Touch terminals
- 14 41X0BkoUP024602.zip OS Update Package v02.46.02 without CleanAppl for Touch and Non-Touch terminals
- 15 41X0BsiUC024602.zip OS Update Package v02.46.02 with CleanAppl for Touch and Non-Touch terminals
- 16 41X0BsiUP024602.zip OS Update Package v02.46.02 without CleanAppl for Touch and Non-Touch terminals
- 17 41X0c70BcpAB024602.APF Airbeam Package v02.46.02 without CleanAppl for Touch, Non-Touch and VoW Terminals
- 18 41X0c70BcpAC024602.APF Airbeam Package v02.46.02 with CleanAppl for Touch, Non-Touch and VoW Terminals
- 19 41X0c70BctAB024602.APF Airbeam Package v02.46.02 without CleanAppl for Touch, Non-Touch and VoW Terminals
- 20 41X0c70BctAC024602.APF Airbeam Package v02.46.02 with CleanAppl for Touch, Non-Touch and VoW Terminals
- 21 41X0c70BdeAB024602.APF Airbeam Package v02.46.02 without CleanAppl for Touch, Non-Touch and VoW Terminals
- 22 41X0c70BdeAC024602.APF Airbeam Package v02.46.02 with CleanAppl for Touch, Non-Touch and VoW Terminals
- 23 41X0c70BfrAB024602.APF Airbeam Package v02.46.02 without CleanAppl for Touch, Non-Touch and VoW Terminals
- 24 41X0c70BfrAC024602.APF Airbeam Package v02.46.02 with CleanAppl for Touch, Non-Touch and VoW Terminals
- 25 41X0c70BitAB024602.APF Airbeam Package v02.46.02 without CleanAppl for Touch, Non-Touch and VoW Terminals
- 26 41X0c70BitAC024602.APF Airbeam Package v02.46.02 with CleanAppl for Touch, Non-Touch and VoW Terminals
- 27 41X0c70BjpAB024602.APF Airbeam Package v02.46.02 without CleanAppl for Touch, Non-Touch and VoW Terminals
- 28 41X0c70BjpAC024602.APF Airbeam Package v02.46.02 with CleanAppl for Touch, Non-Touch and VoW Terminals
- 29 41X0c70BkoAB024602.APF Airbeam Package v02.46.02 without CleanAppl for Touch, Non-Touch and VoW Terminals
- 30 41X0c70BkoAC024602.APF Airbeam Package v02.46.02 with CleanAppl for Touch, Non-Touch and VoW Terminals
- 31 41X0c70BsiAB024602.APF Airbeam Package v02.46.02 without CleanAppl for Touch, Non-Touch and VoW Terminals
- 32 41X0c70BsiAC024602.APF Airbeam Package v02.46.02 with CleanAppl for Touch, Non-Touch and VoW Terminals

7 Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
WT41N0	Windows CE7.0

8 Installation Requirements

WT41N0 device must contain released version of CE7.0 Software

9 Installation Instructions

- 1. Unzip ZIP file and copy its content ('OSUpdate' folder for Touch & Non Touch, 'OSUpdate_VOW' folder for VOW) to the \Temp folder of the terminal.
- 2. Place the device to be upgraded on A/C power supply.
- 3. Navigate to the "\Temp\OSUpdate" folder for Touch & Non Touch terminal and "\Temp\OSUpdate_VOW" folder for VOW terminal. Invoke 41X0c70Bxx_TEMP shortcut.

Important note: The update will take about 1 minute to complete. Please do not remove the device from A/C power during this time.

10 Part Number and Release Date

- 41X0BcpUC024602.zip
- 41X0BcpUP024602.zip
- 41X0BctUC024602.zip
- 41X0BctUP024602.zip
- 41X0BdeUC024602.zip
- 41X0BdeUP024602.zip
- 41X0BfrUC024602.zip
- 41X0BfrUP024602.zip
- 41X0BitUC024602.zip
- 41X0BitUP024602.zip
- 41X0BjpUC024602.zip
- 41X0BjpUP024602.zip
- 41X0BkoUC024602.zip
- 41X0BkoUP024602.zip

- 41X0BsiUC024602.zip
- 41X0BsiUP024602.zip
- 41X0c70BcpAB024602.APF
- 41X0c70BcpAC024602.APF
- 41X0c70BctAB024602.APF
- 41X0c70BctAC024602.APF
- 41X0c70BdeAB024602.APF
- 41X0c70BdeAC024602.APF
- 41X0c70BfrAB024602.APF
- 41X0c70BfrAC024602.APF
- 41X0c70BitAB024602.APF
- 41X0c70BitAC024602.APF
- 41X0c70BjpAB024602.APF
- 41X0c70BjpAC024602.APF
- 41X0c70BkoAB024602.APF
- 41X0c70BkoAC024602.APF
- 41X0c70BsiAB024602.APF
- 41X0c70BsiAC024602.APF

November 26, 2014