

- [Introduction](#)
 - [Description](#)
 - [Contents](#)
 - [Device Compatibility](#)
 - [Installation Requirements](#)
 - [Installation Instructions](#)
 - [Part Number and Release Date](#)
-

Introduction

When device connected with RS419, UPCA barcode is not scanning after Battery Swap and Suspend/Resume

Description

- When device connected with RS419, UPCA barcode is not scanning after Battery Swap and Suspend/Resume

Contents

SPR26647_WT41_C70_en_024602_v1_0_WB.cab

SPR26647_WT41_C70_en_024602_v1_0_NB.cab

Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
WT41	CE 7.0

Installation Requirements

BSP version: 02.46.02

Installation Instructions

For NORMAL installation of the PATCH:

- Copy “SPR26647_WT41_C70_en_024602_v1_0_WB.cab” file to the device.
- Deploy the solution by tapping on the “SPR26647_WT41_C70_en_024602_v1_0_WB.cab” file.
- After successful deployment of the “SPR26647_WT41_C70_en_024602_v1_0_WB.cab” file, device will do an automatic warm boot.

For MSP or REMOTE installation of the PATCH, use

SPR26647_WT41_C70_en_024602_v1_0_NB.cab. This cab will not perform an automatic warm boot.

MSP/Remote Installer is responsible for performing the warm boot.

Part Number and Release Date

N/A

December, 2014