

# Release Notes – Zebra Android 13

### 13-14-21.00-TG-U01-STD-ATH-04 Release (GMS)

# **Highlights**

This Android 13 GMS release 13-14-21.00-TG-U01-STD-ATH-04 covers HC20 and HC50 family of products.

Please see device compatibility under Addendum Section for more details.

### **Software Packages**

Package Name	Description
AT_FULL_UPDATE_13-14-21.00-TG-U01-STD-ATH-04.zip	Full package update
ATH_DELTA_UPDATE_13-14-21.00-TG-U00-STD_TO_13-14-21.00-TG-U01-STD.zip	Delta package update from 13-14- 21.00-TG-U00 TO 13-14-21.00-TG- U01-STD release
Releasekey_6490_EnterpriseReset_V2.zip	Enterprise reset package
Releasekey_6490_FactoryReset_V3.zip	Factory reset package

### **Security Updates**

This build is compliant up to Android Security Bulletin of Oct 01, 2023

### LifeGuard Update 13-14-21.00-TG-U01

- LifeGuard Update 13-14-21.00-TG-U01 contains security updates only.
- > This LG patch is applicable for 13-14-21.00-TG-U00-STD-ATH-04 BSP version.
  - New Features
    - None
  - Resolved Issues
    - None
  - Usage Notes
    - None



### LifeGuard Update 13-14-21.00-TG-U00

This LG patch is applicable for 13-14-21.00-TG-U00-STD-ATH-04 BSP version.

#### New Features

- This is an initial Android 13 GMS release for HC20 and HC50 family of products.
- Initial Beta Release of Zebra Showcase App (Self Updatable) explores the latest features and solutions, a platform for new demos built on Zebra Enterprise Browser.
- DWDemo has moved to the ZConfigure folder.

#### Resolved Issues

- SPR-47751 Resolved an issue with setting the default launcher when Settings app is blacklisted.
- SPR-48241 Resolved an issue with System UI crash with MobileIron's DPC launcher.
- SPR-47645 Resolved an issue with EHS suddenly disappears and Quickstep shows up.
- SPR-48826 Resolved an issue with the notification bar size.
- SPR-48066 Resolved an issue where Excessive debug is filling log files.
- SPR-50027 Resolved an issue with keyboard for not switching to numeric layout.
- SPR-50407 Resolved an issue with EHS which prompted to select launcher frequently.
- SPR-47994 Resolved an issue with EHS where update of title name was slower at every reboot.
- SPR-48592 Resolved an issue with EHS where tapping on home button prompts to select either EHS
  or default launcher even though EHS is set as default home app.
- SPR-50081 Resolved an issue with device which was stopping the scan function, and the only
  resolution was to power off the device and pull the battery out of the device.
- SPR-50146 Resolved an issue where PTT button remapping to power button was not possible.
- SPR-48568 Resolved an issue with Advanced Device Setup, which was staying in Progress for more than 24 hours.
- SPR-50379 Resolved an issue in JS PDF, where disabling ALL Camera was not working.
- SPR-48518 Resolved an issue with StageNow, where FileMgr CSP was not downloading from customer URL over VPN access private server.
- SPR-50983 Resolved an issue where MX app used to fail while clearing recent apps.
- SPR-50161 Resolved an issue with Wifi, where many pings are getting lost during comparison on roaming tests.
- SPR-48699 Resolved an issue where WLAN interface was getting disconnected frequently from Wi-Fi network with Altai AP.
- SPR-48780 Resolved an issue with USB Host manager where it returns invalid configuration rule error.
- SPR-48738 Resolved an issue with HostMgr where modified hostname not responding to ping.
- SPR-48779 Resolved an issue with RxLogger configuration (config.json) that cannot be overwritten.
- SPR 48803 Resolved an issue where MX UI Setting LockOverrideButton throws exception Feature is not supported.
- SPR-50041 Resolved an issue with Datawedge was not supporting RFID Input.
- SPR-50665 Resolved an issue where user was not able to use JS UImgr QuickTileIdentifier WIFI.
- SPR-50766 Resolved an issue with MX which was reporting failure when deploying XML due to permission error.
- SPR-50709 Resolved an issue with SOTI script reset password was changing screen lock to password instead of PIN.
- SPR-51265 Resolved an issue on Speaker phone mode where mic quality is poor.
- SPR-50519 Resolved an issue with Battery Manager shows decommission battery notification.



- SPR-50571 Resolved an issue with Screen rotation where manual screen rotation doesn't rotate the screen.
- SPR-51356 Resolved an issue with where WPA PEAP Wi-Fi profile could not be created without Domain name.
- SPR-48475 Resolved an issue with Bluetooth connectivity issues with DS3678 scanners.
- SPR-50487 Resolved an issue with Connectivity issues with RS5100.
- SPR-50667 Resolved an issue with Bluetooth disconnections with payment pin terminal YOXIMO.

#### Usage Notes

None

#### **Version Information**

Below Table contains important information on versions

Description	Version
Product Build Number	13-14-21.00-TG-U01-STD-ATH-04
Android Version	13
Security Patch level	Oct 01, 2023
Component Versions	Please see Component Versions under Addendum section

## **Device Support**

The products supported in this release are HC20 and HC50 family of products.

Please see device compatibility details under Addendum Section.

### **Known Constraints**

- Delta OTA packages are not supported in Recovery mode. To apply Delta OTA packages, use StageNow/MDM solution.
- Staging via NFC is not supported.
- DHCP Option 119 & Auto PAC Proxy feature is currently not supported in this release. Zebra is working on enabling these 2 features in future Android 13 releases.
- User will not be able to push files into below listed directories using adb command. Alternately, EMM clients or StageNow can be used to push files into below listed directories.
  - o /enterprise/



- Customers using Airwatch Proprietary staging method which includes generation of barcodes from Airwatch console and using external FTP as staging servers not ready for this release, Zebra will enable this feature in upcoming release of Airwatch agent.
- StageNow Desktop smart or Lifeguard feature is not supported for OS Upgrade or OS Downgrade devices.
- Video conference over WEB RTC (Real Time Communication) interpreting solution not supported for lower resolution (SPR-48680).
- Bluetooth SSI mode is not working via customer app using EMDK with DS3678 (SPR-50159).
- Zebra apps do not support Android Work Profiles or any COPE Mode features. Zebra is working on enabling these features in future Android 13 releases.
- Customers using an MDM to configure a PEAP-MSCHAPv2 profile without the CA certificate or without
  the Domain name must use Stage Now to create the desired XML profile. Zebra is working to resolve this
  in the next release so that the same configuration can also be deployed via EMM.
- Third-party ISV can query for the device model using Android property 'android.os.Build.MODEL' or the system property 'ro.product.model' to check if the device is "HC20", "HC50" or "TC22".

### **Important Links**

- Installation and setup instructions (If the link does not work, please copy It to browser and try)
- Zebra Techdocs
- Developer Portal



# **Addendum**

# **Device Compatibility**

This software release has been approved for use on the following devices.

Device Family	Part Number	Device Specific Manuals and Guides
HC20	WLMT0-H20B6BCJ1-A6 WLMT0-H20B6DCJ1-NA	<u>HC20</u>
HC50	WLMT0-H50D8BBK1-A6 WLMT0-H50D8BBK1-NA	<u>HC50</u>



### **Component Versions**

Component / Description	Version
Linux Kernel	5.4.233-qgki
AnalyticsMgr	10.0.0.1006
Android SDK Level	33
Audio (Microphone and Speaker)	0.21.1.0
Battery Manager	1.5.0
Bluetooth Pairing Utility	5.2
Zebra Camera App	2.3.1
DataWedge	13.0.114
EMDK	13.0.4.4304
Files	t_frc_doc_330543000
License Manager and LicenseMgrService	6.0.29 and 6.0.62
MXMF	13.1.0.51
NFC FW	PN7160_AR_11.02.00
OEM info	9.0.0.1005
OSX	QCT6490.130.13.4.13
Rxlogger	13.0.12.27
Scanning Framework	39.45.5.0
StageNow and Zebra Device Manager	13.1.0.51 and 13.1.0.51
WLAN	FUSION_QA_4_1.3.0.008_T FW:1.1.2.0.866.6
Zebra Bluetooth	13.3.7
Zebra Volume Control	3.0.0.93
Zebra Data Service	10.0.7.1001
Zebia Bala cervice	



# **Revision History**

Rev	Description	Date
1.0	Initial release	October 25, 2023