

# Release Notes – Zebra Android Oreo 01-30-04.00-OG-U06-STD Release (GMS)

# **Highlights**

The details of the Android GMS Oreo release 01-30-04.00-OG-U06-STD that covers family of products including TC52, TC57, TC72, TC77, TC52HC, PS20x, TC8300, MC9300, VC8300, L10A, ET51, ET56, EC30 and CC600, CC6000. Please see, Device Compatibility under Addendum Section for more details. LifeGuard patches are cumulative and include all previous fixes that are part of earlier patch releases.

### **Software Packages**

| Package Name                               | Description       |
|--|-------------------|
| HE_DELTA_UPDATE_01-30-04.00-OG-U06-STD.zip | LG Package Update |

### **Security Updates**

This build is Compliant up to Android Security Bulletin of June 01, 2020.

#### LifeGuard Update 06:

- ➤ This LG patch is applicable for 01-30-04.00-OG-U00-STD BSP version. The LG Patch includes the following updated components.
  - MX: 10.0.5.1
  - DataWedge: 8.0.42
  - StageNow-Client: 4.2.6.6
  - MX Proxy Framework: 10.0.1.1
  - Enterprise Browser: 2.7 (for PS20 devices only)

#### **Fixes**

- SPR39784/SPR39879 Resolved an issue wherein setting time zone would not set the time correctly via MX
- SPR39878 Resolved an intermittent crash issue in Datawedge.
- SPR39592 Resolved an issue wherein intermittently the BT Pairing pop up would appear on disconnecting a BT scanner.
- SPR39647 Resolved an issue wherein CODE39 symbology was not being decoded
- SPR39327 Resolved an issue wherein intermittently devices would get stuck in fastboot screen after a Factory reset.

#### **New Features**

- Added eSIM provisioning
- Added support to change the device's domain selection like from voice to data and vice versa.
- Added auto selection of active SIM/USIM/eSIM subscriptions when device is in DSDS mode



#### **LifeGuard Update 04:**

This LG patch is applicable for 01-30-04.00-OG-U00-STD BSP version. The LG Patch includes the following updated components.

• MX: - 10.0.2.6

DataWedge: - 8.0.37

StageNow-Client: - 4.2.5.5

• Enterprise Keyboard: - 2.2.2.3

• EMDK: - 8.0.10.2621

DDT: - 1.20.0.2

• Event injection Service: - 4.3.0.0

• Zebra Folder: -10.0

Wi-Fi: - FUSION QA 2 1.11.0.008 O

OSX: QCT.81.8.25.18

#### **Fixes**

- SPR39012 Resolved an issue wherein the profile with SKIP\_SUW used to take more time to get applied
- SPR39545-Resolved an issue wherein external USB keyboard was not getting disabled via StageNow or MX
- SPR39405- Resolved an issue wherein cellular network connection failure were observed.
- SPR39514-Resolved an issue wherein while using chrome in GMS restricted profile, enable Google Play services notification popup used to appear.
- SPR39613 Resolved an issue where Device was unable to fetch UUID details of remote device
- SPR39513- Resolved an issue wherein screen would not wake up from suspend when using scan-trigger as wakeup source
- SPR39006 Added support to automatically agree to the location consent when the location modes are changed using WirelessMgr CSP
- SPR35665 Resolved an issue wherein Google keyboard settings are not persisting through a reboot when configured directly after factory reset
- SPR38534 Resolved an issue where disconnection is observed in Fast Transition mode when device is in suspend state.
- SPR39082 Resolved an issue wherein Intermittent loss of Ethernet connection is observed.
- SPR38880 Resolved an issue wherein device gets stuck on bootup screen.
- SPR38885 Added support to allow package installation while App whilelist is enabled with App verification mode as long as the package and its corresponding signature is whitelisted.
- SPR39332 Resolved an issue wherein scanning multiple barcodes would not work while in SKIP SETUP Wizard screen
- SPR38739 Resolved an issue wherein streaming of certain MP3 files used to fail
- SPR38748 Resolved an issue wherein multicast voice traffic reception is improved.
- SPR39578-Resolved an issue where Device was unable to retain Bluetooth connection after idle timeout period
- Fixed an issue on SE4750 scanner devices where scanning would occasionally stop after extensive scanning.
- SPR39544 Resolved an issue wherein the eMMC health data was being reported incorrectly for a specific flash part.



• SPR39644 – Included Rxlogger v5.4.16.0 that provides option to store the logs in the Internal sdcard, even when external SDcard is present on the device. User needs to select "Enable Internal sdcard only" to store the logs in the internal sdcard.

#### **New Features**

- Added Workstation Dock Enhancements & PH10 Support.
- Added Ability to Provision network credentials as part of Android Setup Wizard.
- Added support for Google QR Code integration with device scanner.
- Added support for Raw and IrCOMM modes for existing IrDA SW package.
- Added secure DataWedge Intent APIs for device and data security.
- Added support of Dynamic Staging to mass create barcodes from a single profile.
- Added Ability to easily add support for new File Transfer protocols.
- Added support to Control Access to Sensitive MX Functions.
- Added MC93 Cold Storage SKUs Heater Control Logic Optimization.
- Added Scanner Frame support for ET51.
- · Added support for Connectivity analysis retry in Worry Free Wifi.
- Added support for Image Capture with anchor barcode.
- Added support for Sensitivity parameter for Presentation mode.
- Added support for Trigger modes (Timed Release & Timed Hold) support in DS36xx and L36xxx scanners.

### Cellular carrier supported

AT&T, Verizon Wireless, Sprint, Telstra and ROW (Rest of World)

#### **Version Information**

Below Table contains important information on versions

| Description          | Version   |
|----------------------|---|
| Product Build Number | X1-30-04.00-OG-U06-STD                              |
| Android Version      | 8.1.0   |
| Security Patch level | June 1, 2020  |
| Linux Kernel         | 4.4.78  |
| Component Versions   | Please see Component Version under Addendum section |



## Installation

### **Requirements and Instructions**

· Installation and setup instructions

### **Upgrade Options**

Below table provides detailed information on shortest path to upgrade based on current version of software.

| Current Software<br>Version on Device  | Steps to get to this Release  | Comments  |
|--|---|---|
| 01-12-01.00-OG-Uxx<br>01-13-20.00-OG-Uxx<br>01-18-02.00-OG-Uxx<br>01-21-18.00-OG-Uxx | Apply Full Package Update HE_FULL_UPDATE_01-30-04.00-OG-U00-STD.zip Followed by Apply Delta Update HE_DELTA_UPDATE_01-30-04.00-OG-U06-STD.zip   | Full Package<br>Update  |
| 01-23-18.00-OG-Uxx   | Option 1: Apply Delta Package Update HE_DELTA_UPDATE_01-23-19.00-OG_TO_01-30- 04.U00-OG.zip Followed by Apply Delta Update HE_DELTA_UPDATE_01-30-04.00-OG-U06-STD.zip Option 2: Apply Full Package Update HE_FULL_UPDATE_01-30-04.00-OG-U00-STD.zip Followed by Apply Delta Update HE_DELTA_UPDATE_01-30-04.00-OG-U06-STD.zip | Option #1 is recommended as size of Delta package update is smaller compared to Full Package Update |
| 01-30-04.00-OG-Uxx   | Apply Delta Update HE_DELTA_UPDATE_01-30-04.00-OG-U06-STD.zip   |   |

NOTE: The MC93 devices with below HW IDs are not allowed to downgrade to any of the older BSPs than 01.30.04.

HW IDs: 513, 514, 521, 544, 549, 588, 589

The HW ID from MC93 devices can be found under "Settings->System->About phone->SW Components->HW ID"



### **Known Constraints and Workarounds**

- WiFi sleep policy set to "Always" (Android O limitation)
- Enterprise Browser v3.0 is not supported in LG Update 06 for PS20x devices.
- As GMS Restricted Mode is available in this release, Customers using Enable/Disable GMS apps may want to consult the settings types for App Manager, Power Manager and GMS Manager in Zebra's Tech Docs. Functionality originally in Enable/Disable GMS apps (App Manager) has been moved to GMS Restricted Mode (GMS Manager).
- Some devices operate at 320 dpi. This screen configuration results in the majority of the AOSP applications displaying content consistently in both portrait and landscape modes. In most cases if the application layout is not optimal in landscape it is optimal in portrait or vice versa. However, there are a few applications that do not render properly in either portrait or landscape. In this case the suggested alternative is to change the display size using the bundled Display Settings APK or use settings menu to change the display size and font size (settings Display Advanced settings Display Size / Font Size).



# **Addendum**

# **Device Compatibility**

This software release has been approved for use on the following devices.

| Device<br>Family | Part Number  |   | Device Specific<br>Manuals and<br>Guides |
|------------------|--|---|--|
| TC52             | TC520K-1PEZU4P-NA,<br>TC520K-1PEZU4P-A6<br>TC520K-1PEZU4P-FT<br>TC520K-1PEZU4P-IA              | TC520K-1HEZU4P-IA<br>TC520K-1HEZU4P-NA<br>TC520K-1HEZU4P-A6<br>TC520K-1HEZU4P-FT                      | TC52 Home Page                           |
| TC72             | TC720L-0ME24B0-A6<br>TC720L-0ME24B0-NA<br>TC720L-0ME24B0-BR                                    | TC720L-0ME24B0-IA<br>TC720L-0ME24B0-TN<br>TC720L-0ME24B0-FT   | TC72 Home Page                           |
| PS20             | PS20J-P4G1A600<br>PS20J-P4G1NA00<br>PS20J-P4G1A600<br>PS20J-P4G1NA00<br>PS20J-B2G1A600         | PS20J-B2G1A600<br>PS20J-B2G1NA00<br>PS20J-B2G1NA00<br>PS20J-P4H1A600<br>PS20J-P4H1NA00                | PS20 Home Page                           |
| TC57             | TC57HO-1PEZU4P-A6<br>TC57HO-1PEZU4P-NA<br>TC57HO-1PEZU4P-EA<br>TC57HO-1PEZU4P-FT<br>(FIPS SKU) | TC57HO-1PEZU4P-IA<br>TC57HO-1PEZU4P-BR<br>TC57HO-1PEZU4P-ID   | TC57 Home Page                           |
| TC77             | TC77HL-5ME24BG-A6<br>TC77HL-5ME24BG-NA<br>TC77HL-5ME24BG-FT<br>(FIPS SKU)<br>TC77HL-5ME24BD-IA | TC77HL-5ME24BD-ID<br>TC77HL-5ME24BG-EA<br>TC77HL-5MG24BG-EA<br>TC77HL-6ME34BG-A6<br>TC77HL-5ME24BD-BR | TC77 Home Page                           |
| MC9300           | MC930B-GSXXG4XX<br>MC930P-GSXXG4XX<br>MC930P-GFXXG4XX  | MC930B-GSXXG4NA-XX<br>MC930P-GSXXG4NA-XX  | MC9300 Home Page                         |
|                  | Note: 'x' Stands for wild card for different configurations.                                   |   |  |
| ET51             | ET51CE-G21E-00A6<br>ET51CE-G21E-00NA<br>ET51CE-G21E-00IA<br>ET51CE-G21E-SFNA                   | ET51CT-G21E-00A6<br>ET51CT-G21E-00NA<br>ET51CE-G21E-SFA6  | ET51 Home Page                           |



| ET56   | ET56DE-G21E-00A6<br>ET56DE-G21E-00IA  | ET56DE-G21E-00NA  | ET56 Home Page   |
|--------|---|---|------------------|
| CC600  | CC600-5-3200LNNA<br>CC600-5-3200LNWW  | CC600-5-3200LNIN  | CC600 Home Page  |
| CC6000 | CC6000-10-3200LCWW<br>CC6000-10-3200PCWW<br>CC6000-10-3200LCNA<br>CC6000-10-320NLCNA  | CC6000-10-3200PCNA<br>CC6000-10-3200LNNA<br>CC6000-10-320NLCWW  | CC6000 Home Page |
| VC8300 | VC83-08FOCABAABA-I<br>VC83-08FOCQBAABA-I<br>VC83-<br>08FOCQBAABANA  | VC83-08SOCABAABA-I<br>VC83-08SOCQBAABA-I<br>VC83-08SOCQBAABANA<br>VC83-08SOCQBAABAIN  | VC8300 Home Page |
| TC8300 | TC83B0-x005A510NA TC83B0-x005A61CNA TC83BH-x205A710NA TC83B0-x005A510RW TC83B0-x005A61CRW TC83BH-x205A710RW TC83B0-x005A510CN TC83B0-x005A61CCN TC83BH-x205A710CN TC83B0-x005A510IN TC83B0-x005A61CIN TC83BH-x205A710IN TC83BH-x205A710IN | TC83BH-x206A710NA TC83BH-x206A710RW TC83B0-4005A610NA TC83B0-4005A610RW TC83B0-4005A610CN TC83B0-4005A610IN TC83B0-5005A610NA TC83B0-5005A610RW TC83B0-5005A610CN TC83B0-5005A610CN TC83B0-5005A610IN TC83B0-x005A510TA TC83BH-x205A710TA | TC8300 Home Page |
| EC30   | EC300K-1SA2ANA<br>EC300K-1SA2AA6<br>EC300K-1SA2AIA  | KT-EC300K-1SA2BNA-10<br>KT-EC300K-1SA2BA6-10  | EC30 Home Page   |
| L10AW  | RTL10B1-xxAxxX0x00A6<br>(ROW)<br>RTL10B1-xxAxxX0x00IN<br>(India)  | RTL10B1-xxAxxX0x00NA<br>(NA)  | L10 Home Page    |
|        | Note: 'x' Stands for wild care  | d for different configurations.   |                  |



# **Component Versions**

| Component / Description           | Version                                |
|-----------------------------------|--|
| ActiveEdge                        | 2.5.16                                 |
| AnalyticsMgr                      | 2.4.0.1254                             |
| Battery Management                | Version: 1.4.2                         |
| Battery Swap [Enhanced]           | Version: 2.2.0                         |
| Bluetooth Pairing Utility         | Version 3.16                           |
| Device Central                    | 2.1.0.15                               |
| DataWedge                         | 8.0.42                                 |
| Diagnostic Tool                   | 1.20.0.2                               |
| EMDK                              | 8.0.10.2621                            |
| Enterprise Keyboard               | 2.2.2.3                                |
| System Update                     | 1.0.0.8                                |
| MXMF                              | 10.0.5.1                               |
| OSX                               | QCT.81.8.25.18                         |
| StageNow-Client                   | 4.2.6.6                                |
| Wi-Fi                             | FUSION_QA_2_1.11.0.008_O               |
| License Manager and License Agent | version 4.0.2 and version 4.0.31.3.2.0 |
| MSRN                              | 2.01                                   |
| NFC                               | NFC_NCIHALx_ARC0.8.4.0                 |
| PTT Express                       | 3.1.42                                 |
| Rxlogger and RxLoggerUtility      | Version 5.4.16.0 and Version: 1.3.3.12 |
| Scanning Framework                | 23.1.13.0                              |
| Simulscan                         | "Version: 4.0.5"                       |
| WorryFree Wifi Analyzer           | 3.2.13                                 |

Last Revised:06/12/2020