

7505_CE5_6.0.1099

Software Release Notice

10/31/2012

Release Date: 2012.10.31

Release Images: Part

Released @ Iteration 2

7505_WINCE_5_JAPAN_6.0.1099_J262m [1070734]

7505_WINCE_5_MULTI_6.0.1099_J262l [1070730]

7505_WINCE_5_SCH_6.0.1099_J262n [1070731]

7505_WINCE_5_TRAD_CHN_6.0.1099_J262n [1070732]

Release History:

7505_WINCE_5_MULTI_5.9.1029 (wince50Gmm1.1029.1 Released@2012-01-05)

7505_WINCE_5_MULTI_5.5.947 (wince50Gmm1.947.6 Released@2011-05-11)

7527_CE50_E-FIGS_MULTI_5.5.900 (wince50Gmm1.900.1 Released@2010-11-04)

7505_WINCE_5_MULTI_5.3.850 (wince50Gmm1.850.4 Released@2010-07-08)

7505_WINCE_5_MULTI_5.2.825 (wince50Gmm1.825.1 Released@2010-03-24)

7505_WINCE_5_MULTI_5.1.811 (wince50Gmm1.811.3 Released@2010-02-16)

7505_WINCE_5_MULTI_5.0.763 (wince50Gmm1.763.6 Released@2009-12-18)

PX750_CE50_PRO_MULTI_LANG_1.0.630 (PXA270-G2.630.7 Released@2008-12-11)

PX750_CE50_PRO_MULTI_LANG_0.1.594 (PXA270-G2.594.3 Released@2008-07-15)

Build Dependencies:

px750PCon [1.2.951]

px750Keyboard [5.4.903]

px750BooSt [1.2.950]

components/wwan/WWAN_CE5.zip 1.14

7527uP POWER [2.9.949]

7527uP KEYBOARD [2.9.949]

7527BooSt - Signed Ultrasecure [5.5.1081]

7505PCon [7.4938]

7505BooSt [7.4.937] ~ fpga 5.7

7505BooSt [7.4.937]

QFE Level:

/docs/reladmin/PlatformBuilderQFE.xls 1.25

SOFTWARE CHANGES

This section provides a list of software changes made since the last Release.

1099.1

[SCR-17683: WWANUI-even if WWANUI is closed should be able to dial out by physical keypad](#)

[SCR-18588: WWAN UI: Voice tab should be at the front when user select the "Dial" from the tooltip window under Phonebook or Call List](#)

[SCR-19115: WBS-741:WWAN-Voice - Show an indication that a call is in progress when user initiate a call from Phonebook or Call lists](#)

[SCR-20000: Enabling Bluetooth not work properly](#)

[SCR-30915: WBS-741: Unable to launch and close WWANUI using the <Send> and <End> HW keys](#)

[SCR-32380: No way to easily enable F3/F4 when WWAN is enabled](#)

[SCR-34880: Improvements needed to data gateway keyboard wedge to improve speed](#)

[SCR-35209: WWANDbg: Improve user-friendliness](#)

[SCR-35250: USB key is not detected by WinCE 5.0 on Ikon running K091](#)

[SCR-35291: When a TR profile is created on an Ikon using HHP imager the imagers red beam will not function and only the green beam will function but the scanner will not scan barcodes](#)

[SCR-35294: WWAN: Handle changing of network password through dialler UI](#)

[SCR-35295: WWAN: Improve handling of NITZ time updates](#)

- [SCR-35414: Add debug option for WWAN MUX on legacy products](#)
- [SCR-35475: Prepare 7505 MFG Win CE image to test new camera ST VS6735 and ICS driver](#)
- [SCR-35509: Omnii-Release 2.0: WWANUI crashes during Phone, Voice, Data and SMS Interaction](#)
- [SCR-35523: Omnii-Release 2.0: WWAN Driver crashes during Voice and Data Co-existence](#)
- [SCR-35564: Bring PX750 MarvelSDIO8686 driver version in sync with 7545 XT10 version](#)
- [SCR-35595: Identec CF Reader: fails to load with new firmware](#)
- [SCR-35636: integrate Summit 3.3.8 release](#)
- [SCR-35738: Omnii-Release2.0. Allow data connection when there is an Active Voice call on 3G network](#)
- [SCR-35789: WWAN: Allow emergency calls when keyboard is locked](#)
- [SCR-35869: WWAN: Can't dial Australian emergency number 000](#)
- [SCR-35882: On the Neo running CE 5 a customers application is displaying the wrong colors. On other devices the color is fine even on our WAP G3 devices.](#)
- [SCR-35921: NEO WinCE5 Pro Speech - Issue with Total Recall. It did not keep the application. TR profile cannot be found anymore after a cold reset either.](#)
- [SCR-35936: NEO core not correctly reporting the network status in task bar](#)
- [SCR-35956: Correct Coverity errors in WWAN component](#)
- [SCR-35960: Omnii-Release 2.1: WWANUI encountered a problem when user attempt to open phone dialer](#)
- [SCR-36011: Omnii-Release 2.1: WWAN Intermittently getting Modem Failure](#)
- [SCR-36024: Add ability to disable SMS permanently on CE 5 and WM Classic](#)
- [SCR-36082: WWAN: Avoid driver crash under WinCE 5](#)
- [SCR-36108: WWANUI: Avoid unnecessary "Dialing failed" message](#)

CONFIGURATION PARAMETER CHANGES

This section provides a list of configuration / parameters changes made since the last Release.

1099.1

[SCR-35414 \(7505pocketpc, 7527pocketpc, bohicawince\) Improve debug option for MUX for legacy products](#)

Parameters:			
	[HKEY_LOCAL_MACHINE\Software\RIL\MUX] "DisableDebugFile"=dword:1 "DebugFilePath"="\MuxDrv.log" "MaxDebugFileLen"=dword:400		

[SCR-35595, SCR-35250 \(7505pocketpc, 7527pocketpc, bohicawince, px750pocketpc\) SCR-35595: Fixed to detect new Identec CF RFID card](#)

Parameters:			
	There's no such a registry value as default and it's optional to create if in need. [HKLM\Drivers\BuiltIn\PCCARD] DummyRead : dword (value greater than zero to enable Dummy Read, 0 or non-existing to disable it)		

This document is proprietary and as such cannot be disclosed, used, copied, or transmitted without prior consent of Psion Inc.

Copyright Psion Inc. 2012.

