

7505_WM61_7.1.1086

Software Release Notice

7/19/2012

Release Date: 2012.07.19

Release Images: Part

Released @ Iteration 1

7505_WM61_CLA_JAPAN_7.1.1086_F182m [1098881]
7505_WM61_CLA_KOREAN_7.1.1086_F182m [1098882]
7505_WM61_CLA_SCH_7.1.1086_F182m [1098883]
7505_WM61_CLA_TR_CHN_7.1.1086_F182m [1098885]
7505_WM61_PRO_JAPAN_7.1.1086_F182m [1098890]
7505_WM61_PRO_SCH_7.1.1086_F182m [1098892]
7505_WM61_PRO_TR_CHN_7.1.1086_F182m [1098894]

Release History:

7505_WM61_CLA_WWE_7.0.1069 (WM61.1069.2 Released@2012-05-18)
7505_WM61_CLA_WWE_6.0.932 (WM61.932.7 Released@2011-07-18)
7505_WM61_PRO_WWE_ADDON_4.1.803 (WM61.803.2 Released@2010-01-08)
7505_WM61_PRO_WWE_ADDON_4.0.786 (WM61.786.2 Released@2009-10-30)
7505_WM61_PRO_FRA_4.0.786 (WM61.786.1 Released@2009-10-30)
7505_WM61_PRO_FRA_3.0.741 (WM61.741.4 Released@2009-08-20)
7527_UPGRADE_TO_CE5_MULTI_4.0.741 (WM61.741.2 Released@2009-08-04)
7505_WM61_CLA_KOREAN_2.1.724 (WM61.724.1 Released@2009-05-07)
7505_WM61_CLA_SCH_1.0.659 (WM61.659.5 Released@2009-02-27)
7505_WINCE_5_MULTI_4.0.626 (7505.626.4 Released@2008-11-06)
7505_WINCE_5_MULTI_3.0.598 (7505.598.5 Released@2008-07-21)
7505_WINCE_5_MULTI_2.0.585 (7505.585.1 Released@2008-05-09)
7505_WINCE_5_MULTI_0.4.578 (7505.578.3 Released@2008-04-15)
7505_WINCE_5_MULTI_0.3.568 (7505.568.2 Released@2008-03-18)
7505_WINCE_5_MULTI_0.1.536 (7505.536.4 Released@2008-02-19)

Build Dependencies:

components/devicescapeagent/Devicescapeagent_WM6.zip 1.3.1.1
components/TotalRecall/TotalRecallService.zip 1.18.1.3
components/PartnerUp/PartnerUp.zip 1.3.1.1
components/ConfigurationManager/Release.zip 1.10.1.2
Component WWAN : 1085.1_F152p
Component BTRestore Tools.711.1 [3.0.711_C099o] ~
components/BTRestore/BTRestore_WM5.zip 1.2.12.1
AKU 1.5.75

SOFTWARE CHANGES

This section provides a list of software changes made since the last Release.

0 *check-in(s), that is/are italic, has/have configuration or parameter changes.*

1086.1

[SCR-35549: Code 128 options blank in the Ikon scanner options](#)

[- SCR-35792, 35549 \(7505pocketpc, 7527pocketpc\) Fixed SCS CPL Code 128 Blank Display in non-English builds](#)

[SCR-35792: Scanner Settings is not displaying any information under Code 128](#)

[- SCR-35792, 35549 \(7505pocketpc, 7527pocketpc\) Fixed SCS CPL Code 128 Blank Display in non-English builds](#)

[SCR-35854: DbGprs.csv has been updated with an APN that does not work in Italy](#)

[- SCR-35854 \(7505pocketpc, 7527pocketpc\) Check in release candidate WWAN component \(Build 1085.1\)](#)

[- SCR-35854 \(wwan\) Branch Merge: Update GPRS operator database](#)

[- SCR-35854 \(wwan\) Integrate CI-24470: Update GPRS operator database](#)

[SCR-35865: Remove Total Recall UI from CCJK builds on WM 6.1](#)

[- SCR-35865 \(7505pocketpc, 7527pocketpc\) Remove UI components of Total Recall from CCJK images.](#)

[SCR-35871: Update WM 6.1 Add-on Cab version to 7.1.](#)

[- SCR-35871 \(7505pocketpc\) Updated 7505 WM 6.1 Add-on cab version to 7.1.](#)

This document is proprietary and as such cannot be disclosed, used, copied, or transmitted without prior consent of Psion Inc.

Copyright Psion Inc. 2012.