

7505_WM61_7.0.1069**Software Release Notice**

6/13/2012

Release Date: 2012.06.13

Release Images: Part #**Released @ Iteration 2**

7505_WM61_CLA_FRA_7.0.1069_D202r [1098880]
 7505_WM61_CLA_GERMAN_DEU_7.0.1069_D202r [1098879]
 7505_WM61_CLA_ITAL_7.0.1069_D202r [1098896]
 7505_WM61_CLA_SPANISH_ESN_7.0.1069_D202r [1098884]
 7505_WM61_CLA_WWE_7.0.1069_D202r [1098886]
 7505_WM61_PRO_FRA_7.0.1069_D202r [1098888]
 7505_WM61_PRO_GERMAN_DEU_7.0.1069_D202r [1098889]
 7505_WM61_PRO_ITAL_7.0.1069_D202r [1098897]
 7505_WM61_PRO_SPANISH_ESN_7.0.1069_D202r [1098893]
 7505_WM61_PRO_WWE_7.0.1069_D202r [1098895]

Release History:

7505_WM61_CLA_WWE_6.0.932 (WM61.932.7 Released@2011-07-18)
7505_WM61_PRO_WWE_ADDON_4.1.803 (WM61.803.2 Released@2010-01-08)
7505_WM61_PRO_WWE_ADDON_4.0.786 (WM61.786.2 Released@2009-10-30)
7505_WM61_PRO_FRA_4.0.786 (WM61.786.1 Released@2009-10-30)
7505_WM61_PRO_FRA_3.0.741 (WM61.741.4 Released@2009-08-20)
7527_UPGRADE_TO_CE5_MULTI_4.0.741 (WM61.741.2 Released@2009-08-04)
7505_WM61_CLA_KOREAN_2.1.724 (WM61.724.1 Released@2009-05-07)
7505_WM61_CLA_SCH_1.0.659 (WM61.659.5 Released@2009-02-27)
7505_WINCE_5_MULTI_4.0.626 (7505.626.4 Released@2008-11-06)
7505_WINCE_5_MULTI_3.0.598 (7505.598.5 Released@2008-07-21)
7505_WINCE_5_MULTI_2.0.585 (7505.585.1 Released@2008-05-09)
7505_WINCE_5_MULTI_0.4.578 (7505.578.3 Released@2008-04-15)
7505_WINCE_5_MULTI_0.3.568 (7505.568.2 Released@2008-03-18)
7505_WINCE_5_MULTI_0.1.536 (7505.536.4 Released@2008-02-19)

Build Dependencies:

components/devicescapeagent/Devicescapeagent_WM6.zip 1.3.1.1
 components/TotalRecall/TotalRecallService.zip 1.18.1.3
 components/PartnerUp/PartnerUp.zip 1.3.1.1
 components/ConfigurationManager/Release.zip 1.10.1.2
 Component WWAN : 852.1_E190q ~ components/wwan/WWAN_WM5.zip 1.10.1.2
 Component BTRestore Tools.711.1 [3.0.711_C0990] ~
 components/BTRestore/BTRestore_WM5.zip 1.2.12.1
 AKU 1.5.75
 7505PCon [938.2]
 7505BooSt - Signed Ultrasecure [937.3]

Special Instructions

1 Refer to the English Build

SOFTWARE CHANGES

This section provides a list of software changes made since the last Release.

1069.1

- [SCR-35291: When a TR profile is created on an Ikon using HHP imager the imagers red beam will not function and only the green beam will function but the scanner will not scan barcodes](#)
- [SCR-35448: ALPS camera replacement on iKon \(DirectShow camera driver\)](#)
- [SCR-35603: Update add-on cab version number on 7505 WM 6.1 to 7.0.](#)
- [SCR-35613: Update wwan component in release candidate for 7505 WM 6.1.](#)

1069.2

- [SCR-31645: enable All bands after releasing circuit switch data connection\(data_CSD\)](#)
- [SCR-34534: Enable mux by default on HC25 radio for WAP & Ikon](#)
- [SCR-34602: Ikon is unable to turn voltages off on the pins of the external docking port](#)
- [SCR-34797: Daylight saving time change is incorrect](#)
- [SCR-35250: USB key is not detected by WinCE 5.0 on Ikon running K091](#)
- [SCR-35641: Ikon Pro 1069.1 Phone Radio couldn't be turn on at all](#)

CONFIGURATION PARAMETER CHANGES

This section provides a list of configuration / parameters changes made since the last Release.

1069.2

- [SCR-34602 \(7505pocketpc\) Corrected OTG ID pin power behavior in DynamicPortPower mode.](#)

Parameters:				
	Optional: [HKLM\Services\TekDTSvc] DynamicPowerMode : dword (value greater than zero to enable dynamic power) IdDetectDisable : dword (value greater than zero to disable port detection)			

Limitations - Medium or Low priority:

[35858](#)

This document is proprietary and as such cannot be disclosed, used, copied, or transmitted without prior consent of Psion Inc.

Copyright Psion Inc. 2012.

