

# Release Notes – MC21 CE 6.0 Hot Fix BSP v63.34.0024 - An improper Chinese characters display - SPR30090

---

- [Introduction](#)
  - [Description](#)
  - [Contents](#)
  - [Device Compatibility](#)
  - [Installation Requirements](#)
  - [Installation Instructions](#)
  - [Part Number and Release Date](#)
- 

## Introduction

SPR30090 - An improper Chinese characters display.

## Description

HotFix OS v63.34.0024 built with added language related SYSGEN components to resolve the issue.

## Contents

2100acpup633424.zip - OSUpdate Package for MC2180 CE devices including Clean Application.

## Device Compatibility

This software release has been approved for use with the following Zebra devices,

Device	Operating System
MC21	CE 6.0

## Installation Requirements

This SW is intended for MC21 CE6 devices with OS v03.34.23

## Installation Instructions

- Unzip the "2100acpup633424.zip" file and copy its content to the \Application folder.
  - Place the device to be upgraded on A/C power supply.
  - Navigate to the \Application\OSUpdate folder and invoke the 2100c60Acp\_APP shortcut.
  - The update will take about 3-4 minutes to complete. Please do not remove the device from A/C power during this time.
- OR
- Unzip the "2100acpup633424.zip" file and copy its content to the \Storage Card folder.
  - Place the SD card in the device to be upgraded.
  - Place the device to be upgraded on A/C power supply.
  - Navigate to the \Storage Card\OSUpdate and invoke the 2100c60Acp\_SD shortcut.
  - The update will take about 3-4 minutes to complete. Please do not remove the device from A/C power during this time.

## Part Number and Release Date

N/A  
November, 2016