

---

# Release Notes - MC2100 CE 6.0 - 01.34.17\_Loc

---

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

---

## Introduction

From the sales floor to the backroom, the Motorola MC2100 mobile computer has what it takes to affordably automate the capture of inventory data right at the point of work. Leveraging Motorola's Mobility Platform Architecture 2.0, the MC2100 offers plenty of processing power, industry-leading data capture capabilities rugged design, superior ergonomics, flexible data capture options, plus centralized management. And support for Motorola's RhoElements application development platform allows you to create cross-platform applications that work on different mobile computers with different operating systems. MC2100 is available in Wireless LAN (802.11b/g/n) and Batch configuration

## Description

1. Windows CE 6.0 Core OS (v06.00.0000 R3 built on August 2011 QFE baseline)
2. WLAN Fusion Software version X\_1.01.0.0.024R\_CE60C
3. Microsoft Bluetooth stack
4. RhoElements Framework v1.0.2.3
5. RhoElements BasicBrowser v1.0.2 (WLAN configuration only)
6. MSP Agent v7.06.19
7. RD Client v7.06.19
8. DataWedge v3.4.01 (UI build 33049)
9. Wavelink TelnetCE client v7.3.63 (Demo mode - WLAN configuration only)
10. Power Micro v55.64.0001
11. CPLD v1.00

## Contents

1. 2100c60AcpUP013417.zip - OS Update Package v01.34.17 Software (Chinese Professional)
2. 2100c60AcpAB013417.APF - MSP OS Update Package v01.34.17 Software (Chinese Professional)
3. 2100c60ActUP013417.zip - OS Update Package v01.34.17 Software (Chinese Traditional)
4. 2100c60ActAB013417.APF - MSP OS Update Package v01.34.17 Software (Chinese Traditional)
5. 2100c60AdeUP013417.zip - OS Update Package v01.34.17 Software (German)
6. 2100c60AdeAB013417.APF - MSP OS Update Package v01.34.17 Software (German)
7. 2100c60AfrUP013417.zip - OS Update Package v01.34.17 Software (French)
8. 2100c60AfrAB013417.APF - MSP OS Update Package v01.34.17 Software (French)
9. 2100c60AitUP013417.zip - OS Update Package v01.34.17 Software (Italian)
10. 2100c60AitAB013417.APF - MSP OS Update Package v01.34.17 Software (Italian)
11. 2100c60AjpUP013417.zip - OS Update Package v01.34.17 Software (Japanese)
12. 2100c60AjpAB013417.APF - MSP OS Update Package v01.34.17 Software (Japanese)
13. 2100c60AkoUP013417.zip - OS Update Package v01.34.17 Software (Korean)
14. 2100c60AkoAB013417.APF - MSP OS Update Package v01.34.17 Software (Korean)
15. 2100c60ApbUP013417.zip - OS Update Package v01.34.17 Software (Portuguese Brazil)
16. 2100c60ApbAB013417.APF - MSP OS Update Package v01.34.17 Software (Portuguese Brazil)
17. 2100c60AsiUP013417.zip - OS Update Package v01.34.17 Software (Spanish)
18. 2100c60AsiAB013417.APF - MSP OS Update Package v01.34.17 Software (Spanish)
19. 21xxc60AjpCB000000.cab - Japanese keyboard cab file

## Device Compatibility

This software release has been approved for use with the following Motorola devices.

<b>Device</b>	<b>Operating System</b>
MC2100	Windows CE 6.0 Core
MC2180	Windows CE 6.0 Core

## Installation Requirements

MC2100 device must contain a released version of CE 6.0 Software.

# Installation Instructions

## Update through \Storage Card

- Unzip **2100c60AxxUP013417.zip** file and copy its contents (**OSUpdate** folder) to the root folder on SD card.
- Insert the SD card in the device to be updated.
- Place the device to be updated on A/C power supply.
- Run **2100c60Axx\_SD** shortcut from **\Storage Card\OSUpdate** folder to start the update process.

## Update through \Application

- Unzip **2100c60AxxUP013417.zip** file and copy its content (**OSUpdate** folder) to the **\Application** folder.
- Place the device to be updated on A/C power supply.
- Run **2100c60Axx\_App** shortcut from **\Application\OSUpdate** folder to start the update process.

## Notes:

- Keep the device in AC Power during the update process.
- Updating through Temp folder is not supported in MC2100 due to RAM space constraints.
- While using Application partition update method, Application data will be kept intact and OSUpdate folder will also remain after completing the OS Update process.

## Known Issues :

- Japanese Keyboard - special character issue resolved through 21xxc60AjpCB000000.cab

## Part Number and Release Date

2100c60AcpUP013417

2100c60AcpAB013417

2100c60ActUP013417

2100c60ActAB013417

2100c60AdeUP013417

2100c60AdeAB013417

2100c60AfrUP013417

2100c60AfrAB013417

2100c60AitUP013417

2100c60AitAB013417

2100c60AjpUP013417

2100c60AjpAB013417

2100c60AkoUP013417

2100c60AkoAB013417

2100c60ApbUP013417

2100c60ApbAB013417

2100c60AsiUP013417

2100c60AsiAB013417

21xxc60AjpCB000000

January 23, 2011