

Release Notes - MC21XX - Picklist Mode Not Accurate - SPR 25400

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

The patch contains the latest pixdll.dll version 5.15.13.128 for MC21XX devices with 2-D imager.

Description

1. SPR 25400 - Resolved an issue where the barcodes get decoded even when they are not under the crosshair on the MC21XX device with 2-D imager.
2. If an application or the user cleans up ‘\Application’ folder, this .cab solution has to be re-installed.

Contents

SPR25400_MC21XX_Picklist_Mode_NotAccurate_Issue_WithReboot.cab

SPR25400_MC21XX_Picklist_Mode_NotAccurate_Issue_NoReboot.cab

Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC21XX	WinCE 6.0

Installation Requirements

- MC21XX OS Version 01.34.0017
- MC21XX OS Version 03.34.0023

Installation Instructions

For NORMAL installation of the PATCH:

1. Copy “SPR25400_MC21XX_Picklist_Mode_NotAccurate_Issue_WithReboot.cab” file to the device.
2. Deploy the solution by tapping on the .cab file.
3. After successful deployment of the .cab file, device will do an automatic warm boot.

For MSP or REMOTE installation of the PATCH:

Use “SPR25400_MC21XX_Picklist_Mode_NotAccurate_Issue_NoReboot.cab” file. This cab will not perform an automatic warm boot. MSP/Remote Installer is responsible for performing the warm boot

Part Number and Release Date

SPR25400_MC21XX_Picklist_Mode_NotAccurate_Issue_WithReboot.cab

SPR25400_MC21XX_Picklist_Mode_NotAccurate_Issue_NoReboot.cab

May 13, 2014