
Release Notes - MC2180 – CE 6.0 BSP v04.34.0130 - SE655 engine intermittently decodes wrong values while scanning - SPR31890/SPR30310

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

SPR31890/30310 - SE655 engine intermittently decodes wrong values while scanning.

Description

SE655 engine intermittently decodes wrong values while scanning.

Firmware PAAAXS00-009-R00D0.DAT fixes the issue.

Contents

SPR31890_MC21_C6_en_043430_v1_0.zip

Device Compatibility

This software release has been approved for use with the following Zebra device.

Device	Operating System	BSP Version
MC2180 with SE655 Engine	CE 6.0	v04.34.0130

Installation Requirements

This SW is intended for MC2180 CE6 devices with OS v04.34.0130

Installation Instructions

1. Extract and Copy the content of SPR31890_MC21_C6_en_043430_v1_0.zip into \Application in device.
2. Double-click SE655FUPD.exe
3. Navigate firmware PAAAXS00-009-N01D0.DAT [inside folder\Application\ScannerFirmware\Firmware].
4. Press Update and wait for scanner firmware flashing to be complete.

Part Number and Release Date

NA

June, 2017