

---

# Release Notes – MC55E0 WM6.5 BSP v02.57.00 - Enhanced USB driver to support KVL4000 accessory – SPR34400

---

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Release Date](#)

## Introduction

---

SPR34400 - Updated USB driver to support KVL4000 accessories.

## Description

---

Enhanced USB driver to support KVL4000 accessory.

## Contents

---

SPR34400\_MC55X\_WM65\_en\_025700\_v1\_0\_WB.cab (Hotfix package with auto Warm boot)

SPR34400\_MC55X\_WM65\_en\_025700\_v1\_0\_NB.cab (Hotfix package without auto Warm boot)

## Device Compatibility

---

This Hotfix package software release has been approved for use with the following Zebra devices,

Device	Operating System	BSP Version
MC55E0	WM 6.5	v02.57.00

# Installation Requirements

---

This SW is intended for MC55E0 WM 6.5 devices with OS v02.57.00

## Installation Instructions

---

### **For Normal installation of the PATCH:**

1. Copy "SPR34400\_MC55X\_WM65\_en\_025700\_v1\_0\_WB.cab" file to the application folder/SD card on the device by using Microsoft Active Sync or Mobile Device Center.
2. Navigate on the device to the application folder/SD card.
3. Deploy the solution by tapping on the "SPR34400\_MC55X\_WM65\_en\_025700\_v1\_0\_WB.cab" file.
4. After successful deployment of the "SPR34400\_MC55X\_WM65\_en\_025700\_v1\_0\_WB.cab" file, device will do an automatic warm boot.

### **For MSP or REMOTE installation of the PATCH:**

1. Set up MDM (MSP, Soti, Airwatch, etc..) to send "SPR34400\_MC55X\_WM65\_en\_025700\_v1\_0\_NB.cab" file to the application folder of the device.
2. To deploy the solution, setup in MDM to install the cab file "SPR34400\_MC55X\_WM65\_en\_025700\_v1\_0\_NB.cab" file.
3. Changes will take effect after a manual reboot of the terminal or if MDM reboots device.

## Release Date

---

June 2018