
Release Notes – SPR 23815 – Blue Tooth loss connection after critical Suspend

[Introduction](#)

[Description](#)

[Device Compatibility](#)

[Installation Instructions](#)

[Release Date](#)

Introduction

This posting is for MC75/MC75A WM6.5 devices.

Description

This posting fix the issue of the critical suspend (low power/battery door open) resulted in the Bluetooth chip being left in an invalid state.

Device Compatibility

This software release has been approved for use with the following Motorola devices:

Device	Operating System	OEM Version
MC75	Windows Mobile 6.5	
MC75A	Windows Mobile 6.5	

Installation Instructions

1. For MC75, copy “BTExplorer_2.1.1.27990_MPA1_5.cab” onto the device using Active Sync.
For MC75A, copy “BTExplorer_2.1.1.27990_MPA2.cab” onto the device using Active Sync.
2. On the device, browse to the file and tap CAB file.
3. On the File Dialog, press OK.
4. Follow on screen instructions to complete installation.

NOTE: At the end of installation the device will reboot to complete the installation.

Release Date

October 2013