

---

# Release Notes -- MC9190 Function State Lock SPR23705, SPR23960

---

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

---

## Introduction

Unable to lock the function state for MC9190 WM/CE

## Description

Using this patch you will be able to lock function state by double press function key..

## Contents

23705.cab - for worldwide WM6.5

23705\_woBoot.cab - for worldwide WM6.5

23960.cab - - for worldwide CE6.0

23960\_woBoot.cab - for worldwide CE6.0

23960\_KoreanOS.cab – for Korean CE6.0 image

23960\_KoreanOS\_woBoot.cab - for Korean CE6.0 image

## Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC9190	Windows Mobile 6.5 OEM 41 and CE 6.0 OEM32 worldwide + Korean Localized Image

## Installation Requirements

n/a

## Installation Instructions

\*\*\*.CAB : Copy the file to the device and double click on it. Confirm for all overwrite suggestions. Device will be rebooted automatically when installation completed.

\*\*\*\_woBoot.CAB: Copy the file to the device and double click on it. Confirm for all overwrite suggestions. Cold boot the device manually after the installation completed.

## **Part Number and Release Date**

July 8, 2013

## **Notes:**

To have the Function lock enabled the following registry should be applied:  
[HKEY\_LOCAL\_MACHINE\Hardware\DEVICEMAP\KEYBD]  
"FuncLockState"=dword:00000000

The patch has known issue for CE6.0: when Function locked, Shift locked icon displayed as well. The issue is cosmetic only, the device works according to Function lock rules.