

Release Notes – SPR 25679 – MC91N0 CE6.0 keypad issues

[Introduction](#)
[Description](#)
[Contents](#)
[Device Compatibility](#)
[Installation Requirements](#)
[Installation Instructions](#)
[Part Number and Release Date](#)

Introduction

This patch is coming to fix few keypad issues found on v03.37.02

Description

The following issues are being fixed:

- _ Alpha led is activated when shift key is pressed
- _ Keypad continues to work after warm boot even after disabling via ctlpanel.
- _ Shift key not working as intended after press Shift key twice and press alpha key and then shift key
- _ Up on Func (Blue) Key pressed twice observed shift key in lock state along with blue key in (hallow)
- _ In 43-keypad type, ALT+d displays improper ASCII value
- _ Set Alpha mode-True for Non QWERTY Keyboards not working
- _ Quick pressing keys on the hardware keyboard - producing multiple inputs (doubled input)

Contents

SPR25679_Keyboard.cab

Device Compatibility

This software release has been approved for use with the following Symbol devices.

Device Operating Sys tem

MC9190 CE 6.0 v03.37.02

Installation Requirements

n/a

Installation Instructions

1. Copy **cab** file to the device
2. Install **cab** file by double click on it.

Part Number and Release Date

n/a

June, 2014.