

MC9100 OPERATING SYSTEM WM BSP 2.41.03 AND CE BSP 02.32.04 - HOTFIX CFE 1.0 RELEASE NOTES

1 INTRODUCTION

This patch addresses following issue: When MC9190 terminal is inserted into cradle, ActiveSync connection over serial doesn't auto-initiate, it works only when "Windows\repllog.exe" is tapped.

2 DESCRIPTION

1. As part of the fix, serial driver of MC9190 device is being modified and updated version of the "amagansett_serial.dll" is included in the .cab solution.
2. If an application or the user cleans up device, this .cab solution has to be re-installed.

3 CONTENTS

FIX_SPR23532_MC9190_WM_SerialActiveSyncIssue_NoReboot.cab

FIX_SPR23532_MC9190_WM_SerialActiveSyncIssue_WithReboot.cab

FIX_SPR23532_MC9190_CE_SerialActiveSyncIssue_NoReboot.cab

FIX_SPR23532_MC9190_CE_SerialActiveSyncIssue_WithReboot.cab

4 DEVICE COMPATIBILITY

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC9190	Windows Mobile 6.5/Windows CE6.0

5 INSTALLATION REQUIREMENTS

MC9190 flashed with BSP41.03 (WM OS Version) or OEM Version 02.32.03 (CE OS Version) and later versions.

6 INSTALLATION INSTRUCTIONS

For NORMAL installation of the PATCH:

1. Copy "FIX_SPR23532_MC9190_WM_SerialActiveSyncIssue_WithReboot.cab" file for the **WM OS version** or "FIX_SPR23532_MC9190_CE_SerialActiveSyncIssue_WithReboot.cab" file for the **CE OS version of the terminal by using ActiveSync.**
2. Deploy the solution by tapping on the .cab file.
3. After successful deployment of the.cab file, device will do an automatic reboot.

For MSP or REMOTE installation of the PATCH:

1. Copy "FIX_SPR23532_MC9190_WM_SerialActiveSyncIssue_NoReboot.cab" file for the **WM OS version** or "FIX_SPR23532_MC9190_CE_SerialActiveSyncIssue_NoReboot.cab" file for the **CE OS version of the terminal by using ActiveSync.**
2. Deploy the solution by tapping on the .cab file.
3. Change will take effect after a manual reboot of the terminal is done.

7 PART NUMBER AND RELEASE DATE

FIX_SPR23532_MC9190_WM_SerialActiveSyncIssue_NoReboot.cab

FIX_SPR23532_MC9190_WM_SerialActiveSyncIssue_WithReboot.cab

FIX_SPR23532_MC9190_CE_SerialActiveSyncIssue_NoReboot.cab

FIX_SPR23532_MC9190_CE_SerialActiveSyncIssue_WithReboot.cab

April 19, 2013