
Release Notes – MC92 CE7.0 – BSP v05.57.16 - Elemez icon is missing from Start -> Programs – SPR32172

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

SPR32172 - When installing elemez.cab to application folder after a cold boot the Elemez icon is missing from Start -> Programs.

Description

To resolve this issue, please use the cold boot persistent version of elemez cab files
SPR32172_MC92_C70_en_055716_WB.cab/ SPR32172_MC92_C70_en_055716_NB.cab.

Contents

SPR32172_MC92_C70_en_055716_WB.cab - elemez.cab v1.0.0.381 with auto reboot cab file

SPR32172_MC92_C70_en_055716_NB.cab - elemez.cab v1.0.0.381 without auto reboot cab file

Device Compatibility

This software release has been approved for use with the following Zebra devices,

Device	Operating System	BSP
MC92N0	CE 7.0	v05.57.16

Installation Requirements

MC92N0 device must contain a released version of CE 7.0 with BSP v05.57.16.

Installation Instructions

For Normal installation of the PATCH:

1. Copy " SPR32172_MC92_C70_en_055716_WB.cab " file to the application folder on the device by using Microsoft Active Sync or Mobile Device Center.
2. Navigate on the device to the application folder.
3. Deploy the solution by tapping on the " SPR32172_MC92_C70_en_055716_WB.cab " file.
4. After successful deployment of the " SPR32172_MC92_C70_en_055716_WB.cab " file, device will do an automatic warm boot.

For MSP or REMOTE installation of the PATCH:

1. Set up MDM (MSP, Soti, Airwatch, etc..) to send " SPR32172_MC92_C70_en_055716_NB.cab" file to the application folder of the device.
2. To deploy the solution, setup in MDM to install the cab file " SPR32172_MC92_C70_en_055716_NB.cab" file.
3. Changes will take effect after a manual reboot of the terminal or if MDM reboots device.

Part Number and Release Date

N/A

May 18, 2017