

Release Notes - MC9596 WM6.5 - BSP v60.47.0020 - SHA2 Support For Spanish Localized OS Version - SPR 29084

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

This OS hotfix image addresses SPR29084 – MC9596 SHA2 Support. This OS Hot fix includes a new AKU build no. 29315 from Microsoft that contains the support for recognizing the SHA2 certificate through Cryptographic APIs (CAPIs).

Description

The issue is seen on MC9596 device running WEH6.5 based OS image. SHA2 certificate does not get recognized properly. When trying to install any root SHA2 certificate, the certificate gets installed in intermediate section rather than the root section. Also due to the certificate issue, Microsoft exchange server email sync does not happen.

Contents

95x6w65HsiUL604720.zip

Device Compatibility

This software release has been approved for use with the following Zebra devices,

Device	Operating System
MC95x6	WM 6.5

Installation Requirements

- MC95x6 with BSP 06.47.12 or earlier

Installation Instructions

For NORMAL installation of the OS Hotfix image:

1. Unzip and copy the content to either \Temp or \Storage Card of the device.
2. Start the OS update by clicking the StartUpdLdr.exe file.
3. StartUpdLdr.exe will update the OS image and device will automatically cold boot.

Part Number and Release Date

N/A

March 29, 2016