

# **Special Operating Instructions for Applying Patch of MT2000 ADCServices Version 1.0.0.24**

---

This document describes how to apply the patch of ADCService DLL Version 1.0.0.24 to fix Nixdorf A no error beep on transmission timeout and incorrect default timeout value.

## **Applying the Hotfix:**

### **a. Patch Files**

There will be one file in the patch package

- (1) adcservice.dll – ADCService DLL;

### **b. Applying the Hotfix**

- (1) ActiveSync the scanner to a PC;
- (2) Open up the "Platform" folder on the device using "Explore" on ActiveSync;
- (3) Copy the DLL file to "\Platform" folder;
- (4) Cold boot the scanner (by press and hold scan trigger and '2' key. Wait for screen going black the 2<sup>nd</sup> time and release the trigger and key. Or, just remove the battery and reinsert it to cold boot.)
- (5) The scanner should boot up with the patch applied.