
Release Notes – SB1 CE 6.0 - Airbeam Hot Fix OSUpdate Package v62.01.37 - SPR 31506

[Introduction](#)

[Description](#)

[Contents](#)

[Device Compatibility](#)

[Installation Requirements](#)

[Installation Instructions](#)

[Part Number and Release Date](#)

Introduction

This Hot Fix BSP v62.01.37 is based on BSP v02.01.36

Description

SPR 31506 - OSUpdate using FTPS fails with error message INSUFFICIENT DEVICE MEMORY.

Note: If we upgrade or downgrade OSUpdate Package from v01.01.27, v02.01.36, v02.01.39, v03.01.45 to v02.01.36 over the air using FTPS, the update will fail. Please use v62.01.37 in this case.

Contents

TSDxc60AenAB620137.APF (OSUpdate Package file for deployment using AirBeam)

Device Compatibility

This software release has been approved for use with the following Zebra devices,

Device	Operating System
SB1	Windows CE 6.0

Installation Requirements

SB1 device must contain a released version of CE 6.0

Installation Instructions

For MSP or REMOTE installation of the PATCH:

1. Upload the "TSDxc60AenAB620137.APF" package into MSP server.
 2. Create a bundle using the "TSDxc60AenAB620137.APF" package.
 3. Create a staging profile using "TSDxc60AenAB620137.APF" bundle.
 4. Generate PDF barcode.
 5. Scan barcode using RD Client utility from device to deploy the package.
 6. Once the package is successfully deployed on the device, terminal will do a reboot.
-

Part Number and Release Date

N/A

March, 2017
