

MT20X0 AMBIGUOUS CHARGING LED STATE INDICATOR ERROR HOTFIX RELEASE NOTES, VERSION 0.0.0.10

DESCRIPTION

This hotfix fixes the issue that, when MT2070 or MT2090 is in cradle charging, the state of battery actually being discharged is not indicated.

DEVICE COMPATIBILITY

MT2070

MT2090

RELEASE NOTES

VERSION V0.0.0.10

This hotfix fixes the issue that, when MT2070 or MT2090 is in cradle charging, the state of battery actually being discharged is not indicated.

COMPONENTS

The installed file should be in the following folder on the scanner.

Component	Location
Battdrvr.dll	\Platform\

INSTALLATION

The following is the procedure to apply the Hotfix. It is assumed that the ActiveSync installed on the PC.

- 1) ActiveSync the scanner to a PC;
- 2) Open up the “Platform” folder on the device using “Explore” on ActiveSync;
- 3) Copy the Battdrvr.DLL and Battdrvr.cpy files to “Platform” folder:
- 4) Cold boot the scanner (by press and hold scan trigger and ‘2’ key. Wait for screen going black the 2nd time and release the trigger and key. Or, just remove the battery and reinsert it to cold boot.)

The scanner should boot up with the Hotfix applied.