



VC6090 OPERATING SYSTEM BSP 81.38.0010 - HOTFIX CFE V06.00.00 RELEASE NOTES

INTRODUCTION

Release Notes - SPR27107 - VC6096 - keyboard gets locked when rapidly pressing the brightness “-“ rocker

DESCRIPTION

Once the VC6096 is booted and running, rapidly pressing the brightness “-“ rocker multiple times causes the keyboard and all keys, including the power key to lock up. The unit must be cold booted to recover from the keyboard lockup.

Support for Tianma display added

CONTENTS

SPR26313_VC6096_W61_65_en_080109_v_6_0_NB.cab

SPR26313_VC6096_W61_65_en_080109_v_6_0_WB.cab

DEVICE COMPATIBILITY

This software release has been approved for use with the following Symbol devices.

Device	Operating System
VC6096	WM6.1, WM6.5

INSTALLATION INSTRUCTIONS

Copy cab file to the device and run it.

If you are using the version without boot, then boot the device manually after instalaltion

PART NUMBER AND RELEASE DATE

February, 2015