



# MC9090 OPERATING SYSTEM BSP 01.35.02 WINDOWS MOBILE 5.0 PREMIUM - LOCALIZED RELEASE NOTES

## INTRODUCTION

The Update Loader Image 01.35.02 contains the software required to update a MC9090 device to the latest released software (REV G).

The flagship MC9090 is a rugged handheld mobile device that incorporates a PDA, computer, scanner and imager in a single unit designed for the rigors of all-day, everyday usage.

The MC9090 has Intel X-Scale Bulverde 624MHz processor and delivers the latest version of the Microsoft WM 5.0 Premium Edition operating system.

## DESCRIPTION

### General Enhancements

1. Fusion Radio SW suite version 2.5.1.0.062R2 – For DFS(Dynamic Frequency Selection) Regulatory compliance

### Changes and Fixes in Fusion 2.5.1.0.062R2

1. Compliant with FCC DFS requirements.
2. Fixed public API function S24\_GET\_CHANNEL\_QUALITY to use the correct statistics variables.
3. Fixed single AP topology and sporadic re-authentication failures
4. Fixed public API command USER\_CREDENTIAL\_WLAN\_OVERRIDE to work with user profiles.
5. Fixed rapid switching of profiles with Public API disabling radio.
6. Fixed driver re-authentication issue with CAM mode



## CONTENTS

Localized files

9090w50LcpUA013502.zip Simplified Chinese

9090w50LctUA013502.zip Traditional Chinese

9090w50LdeUA013502.zip German

9090w50LfrUA013502.zip French

9090w50LitUA013502.zip Italian

9090w50LjpUA013502.zip Japanese

9090w50LkoUA013502.zip Korean

9090w50LsiUA013502.zip Spanish

## DEVICE COMPATIBILITY

This software release has been approved for use with the following Symbol devices.

Device	Operating System
MC9090w50	Windows Mobile 5.0 Premium

## INSTALLATION REQUIREMENTS

The device must contain a released version of the SW (not a Beta version).

## PART NUMBER AND RELEASE DATE

June 19, 2007