



MC9200 OPERATING SYSTEM BSP 00.55.11 RELEASE NOTES

INTRODUCTION

Update Loader Image v00.55.11 is a software update for MC92N0 WM6.5 Premium devices using the SE4750 scan engine. This version adds support for the SE4750 scan engine.

DESCRIPTION

1. Operating System: WM 6.5.3 AKU_29326
2. CPU Speed OMAP4430 ES2.3 1 GHz
3. FLASH– eMMC 2GB
4. RAM SDRAM LPDDR2 1GB
5. Added SE4750SR, SE4750MR, SE4750HD Scan Engines support
6. Fusion Radio SW suite X_2.02.0.0.019R, ROW4
7. BT:
 - Microsoft – MSFT 4.0 (default)
 - BT Explorer (SS1) v2.1.1 Build 28342
8. RD Client v7.08.42
9. Data Wedge v3.7.04

CONTENTS

92N0w65LenUP005511.zip	Update Loader Package v00.55.11
92N0w65LenAB005511.apf	AirBEAM Package v00.55.11

DEVICE COMPATIBILITY

This software release has been approved for use with the following Zebra devices.

Device	Operating System
--------	------------------



MC92N0	Windows Mobile 6.5 Classic
--------	----------------------------

INSTALLATION REQUIREMENTS

MC92N0 device must contain released version of WM6.5 Software.

INSTALLATION INSTRUCTIONS

1. Unzip the Update Loader Package (i.e 92N0LenUP005511.zip) and copy its content to the \Storage Card folder.
2. Place the SD card in the device to be upgraded.
3. Place the device to be upgraded on A/C power supply.
4. Navigate to the \Storage Card folder and invoke the StartUpLdr.exe.
5. The update will take about 34 minutes to complete. Please do not remove the device from A/C power during this time.

OR

1. Unzip the Update Loader Package (i.e 92N0LenUP005511.zip) and copy its content to the \Temp folder.
2. Place the device to be upgraded on A/C power supply.
3. Navigate to the \Temp folder and invoke the StartUpLdr.exe.
4. The update will take about 34 minutes to complete. Please do not remove the device from A/C power during this time.

PART NUMBER AND RELEASE DATE

92N0w65LenUP005511

92N0w65LenAB005511

16 July, 2015