XPLORE TECHNOLOGIES

Motion Computing Software Release Note

Name	**Sierra Wireless MC8355 (Gobi3000) Driver Package**
File Name	**Sierra_Wireless_MC8355_Win7_32-64bit_3.16.1311.4013.zip**
Release Date	August 12, 2014
This Version	13.10.1050.53 (3.16.1311.4013 – B4018)
Replaces Version	All previous versions
Intended Users	**J3500/J3600, C5v/F5v/C5t/F5t/C5te/F5te, CL900/CL910**
Intended Product	J3500/J3600, C5v/F5v/C5t/F5t/C5te/F5te, CL900/CL910
File Size	61 MB
Supported Operating System	Windows 7 (32-bit/64-bit)

Fixes in this Release

- Location sensor power management support
- Location sensor USB composition support
- 2G signal strength reporting
- BSOD after power management

What's New in this Release

- Added HSPA+ display support to Windows UI

Known Issues and Limitations

- This is the last driver package with support for MC8355 (Gobi3000)

Installation and Configuration Instructions

To install MC8355 (Gobi3000), perform the following steps:
1. **Disable Mobile Broadband** on the **Wireless tab** in **Motion Dashboard**
2. **Uninstall** any previously installed **Qualcomm Gobi Single Installer Package** through **Control Panel → Programs and Features**
3. Click **download** to save the **MC8355 DriverPkg** to the directory of your choice.
4. **Unzip** the file to a location on your local drive.
5. Double-click **Setup.exe** and follow the prompts
6. **Enable Mobile Broadband** on the **Wireless tab** in **Motion Dashboard**
   The following devices will be installed
   - Sierra Wireless WWAN Device
   - Sierra Wireless DM Port (COMx)
   - Sierra Wireless NMEA Port (COMx)
   - Sierra Wireless WWAN Modem
   - Sierra Wireless Mobile Broadband Network Adapter

Licensing

Refer to your applicable end-user licensing agreement for usage terms.