MT2090 Device Configuration Packages v1.0

Contents

Description

Thank you for selecting Motorola as your mobility solution tool provider. MT2090 Device Configuration Packages (DCP) is used to configure and customize software running on MT2090 scanner.

For the latest software updates, go to the **Support Central** web site and select Software Downloads.

Thank you,

The Motorola Enterprise Mobility Software Development Team

Back to Top

Device Compatibility

MT2090

Back to Top

Release Notes

<u>Version v1.0</u>

1. First release of the Device Configuration Packages (DCP) for MT2090.

Back to Top

Components

If the default install location is not changed, the components are installed in the following folders:

Component	Location
TCM application	\Program Files\Motorola\TCM2\tcm.exe
OSUpdate application	\Program Files\Motorola Device Configuration Packages\MT2090c50Aen\V1.0\ActiveSyncOSUpdateMT2090.bat
Keypad configuration software source code	\Program Files\Motorola Device Configuration Packages\MT2090c50Aen\V1.0\Tools\kbtool *.*
DCP configuration files	\Program Files\Motorola Device Configuration Packages\MT2090c50Aen\V1.0\FlashFolders*.*
Integrator's Guide	\Program Files\Motorola Device Configuration Packages\MT2090c50Aen\V1.0*.pdf

* The Manuals require Adobe Acrobat Reader which can be downloaded from the Adobe web site at: http://www.adobe.com

Back to Top

Installation

Device Configuration Packages are stand-alone products that do NOT require the installation of any other development tools. This DCP has been tested on Windows XP.

Device Configuration Packages support side-by-side installation. Each new version can be installed without uninstalling older versions. This allows the developer to work with several different versions on the same development PC.

The installed DCP components can be easily accessed using the "Motorola Device Configuration Packages" program group on the Windows Start Menu.

Back to Top

Notes

1. **Slow TCM builds** - Some versions of anti-virus software may cause the build script process of TCM to run slowly. To prevent this situation, disable the anti-virus software during builds.

Back to Top

Late Additions

Back to Top

Last revised: December 04, 2009

Copyright (c) 2003-2007
Motorola, Inc.