Xplore Technologies Software Release Note

Name	**Intel USB 3.0 Driver**
File Name	**USB3.0_4.0.4.51.zip**
Release Date	May 9, 2016
This Version	4.0.4.51
Replaces Version	All previous versions
Intended Product	iX101B1 (Bobcat)
File Size	5.4 MB
Supported Operating System	Windows 7

Fixes in this Release

- USB devices may take more than 10 seconds to work after system boot and if the devices are connected behind an USB3.0 Hub.
- USB3.0 device may disappear after resuming from S3.
- A specific USB2.0 thumb drive may disappear from device manager if a file transfer is initiated after formatting the device.

What's New in this Release

- N/A

Known Issues and Limitations

- N/A

Installation and Configuration Instructions

To install USB 3.0 4.0.4.51, perform the following steps:
1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Double-click the installer (setup.exe) and follow the prompts.

Licensing

Refer to your applicable end-user licensing agreement for usage terms.