XPLORE TECHNOLOGIES

Xplore Technologies Software Release Note

Name	**Intel Wireless LAN Driver**
File Name	**Intel_WLAN_Win8.1-64bit_v17.16.0.4.zip**
Release Date	May 12, 2015
This Version	17.16.0.4
Replaces Version	All previous versions
Intended Users	**Motion CL920, R12, C5te/F5te, and C5m/F5m users**
Intended Product	Motion CL920, R12, C5te/F5te, and C5m/F5m Tablet PCs ONLY
File Size	106 MB
Supported Operating System	Windows 8.1 (64-bit)

Fixes in this Release

- Regulatory profile programming issue
- Unable to connect to certain Aps
- 802.11gn and Bluetooth communications conflict

What's New In This Release

- None

Known Issues and Limitations

- BTHS is not installed on new installations starting with 17.0. Upgrades for existing 3160/7260 are supported

Installation and Configuration Instructions

To install WLAN driver package, perform the following steps:
1. Download the update and save to the directory location of your choice.
2. Unzip the file to a location on your local drive.
3. Double-click the installer (setup.exe) and follow the prompts.

Licensing

Refer to your applicable end-user licensing agreement for usage terms.