Release Notes – MC67NA WM 6.5 - Hot Fix BSP v64.56.14

1 Introduction

This Hot Fix BSP v64.56.14 is based on BSP v04.56.13.

2 Description

This Hot Fix BSP v64.56.14 includes the following SPRs fixes:

SPR NO	Synopsis
28381	MC67NA Volume difference.
28853	Device sending wrong key values when using numeric keypad.
28105	PowerKey Action menu screen does not auto-suspend the device in cradle.

Known issue:

Hotfix os is based on MC67NA WM 04.56.13 rebranded OS. Known issue of MC67NA WM 04.56.13 rebranded OS will be applicable for Hotfix OS v64.56.14 also.

3 Contents

67NAw65HenAB645614.zip - Package includes the Upload instructions for MSP installation. AirBeam.

67NAw65HenZP645614.zip - There are 2 packages included in a ZIP file -Partition Table & FPGA as one package and OS package along with instructions.

4   Device Compatibility

This software release has been approved for use with the following Zebra devices,

Device	Operating System
MC67NA	WEH6.5

5   Installation Requirements

MC67NA device must contain a released version of Microsoft WEH 6.5 Professional

6   Installation Instructions

1. OS Package update:
Please see INSTRUCTIONS.txt which is part of 67NAw65HenZP015604.zip.

2. MSP OS Package update
Please see MC67_MSP_Installation_Instructions which is part of 67NAw65HenAB015604.zip for update through MSP.

7   Part Number and Release Date

N/A

April 2016