Motion

Motion Computing Software Release Note

Name	**Intel Advanced Host Controller Interface Driver**
File Name	**Intel_SATA_AHCI_32.zip** **Intel_SATA_AHCI_64.zip**
Release Date	April 12, 2011
This Version	10.1.0.1008
Replaces Version	All previous versions
Intended Users	**Motion C5v, F5v, and J3500 users**
Intended Product	Motion C5v, F5v, and J3500 Tablet PCs ONLY
File Size	206 Kb (32-bit), 238 Kb (64-bit)
Supported Operating System	Windows 7 (32-bit/64-bit)

Fixes in this Release

- 0x9F or 0x7A BSOD seen during Stress Test
- Optical Disk Drive takes a long period of time to eject the tray when Eject command is issued from PowerDVD and iTunes

What's New In This Release

Known Issues and Limitations

Installation and Configuration Instructions

To install this version update, perform the following steps:
1. Download the selected OS version file at the top of this document and save to the directory location of your choice.
2. Unzip file to a location on your local drive.
3. In Device Manager, within IDE ATA/ATAPI Controllers, select to update the "Intel® 5 Series 6 Port SATA AHCI Controller" driver and point to the location where you unzipped the file in step 2.

Licensing

Refer to your applicable end-user licensing agreement for usage terms.